1993

COMMISSION

Property in Sec.

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 19

RECE	VEB	FOR	RECO	R

on per so the Refit

_	10 http://erec. 100 miles
0	USER'S 5 13 140 30
	Elder is a second of the
	State of the State
	A A FEW COLOR STORMS
	• • • •
	att.
	and the second
egis	ster of Deeds Stamp & File Number

For corners in LAPEER Located In: Corner Code ## (County) T 10N R 12E 1. Public Land Survey _ R R 2. Property Controlling т in Section ___ T ____ R . Miscellaneous S __ T .____ R .

4. Lot No. $_$, Recorded Plat $_$ 5. Private Claims __

I, Earl E. Gravlin , in a field survey on . <u>October</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-11. Northeast corner Section 36. History: East town lines run by Joseph Wampler, 1821. Page 670 North west and south lines run by Hervey Parke 1833 page 667. Subdivision of township run by Hiram Burnham, 1834. page 667. Witnesses Hemlock 8 S6°W .24 Beech 9 N75.5°W 3.5 set post. County Surveyors Record: Nothing. Recorded surveys Nothing. Unrecorded surveys Kay 3/26/85 30-10-13

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: Slightly rolling farmland. Intersection Peck Road(bit) and Cade Road(gravel)

Found 1/2 " iron in place

Good occupation appears to be common corner.

MEASUREMENT M-11 TO M-12 2624.91 M-11 TO M-9 5212.54 M-11 TO A-10(10-13) 2606.27 M-10 TO M-9 2639.27

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 15, 1993

Found 1/2 " iron in place, set brass cap

S40°E 71.15' NAIL & TAG N SIDE POWER POLE S40°E 41.10' 2" PIPE ROAD SIGN

S40°W 62.70' FACE GTE JUNCTION BOX

N30°W 51.10 FACE GTE JUNCTION BOX

Lapeer County Road Commission Set Monument Box

FARLE GRAVLIN rof. Surveyor No. 23510 PROFESSION^P

Signed by

Surveyor's Michigan License No. _

Date 12-2-93

VED BY MICHIDAN STATE BOARD OF LAND SUBVEYORS, JAN. 28, 1971 REVISED JAN., 1983

LIBER 005 PAGE 30