SURVEY & REMONUMENTATION

FEB 2 6 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Leelanau Located In: Corner Code # Barbara Kirt • Leelanau Res of Deeds	12/30/97
1. Public Land Survey T_28NR 12W	s 2:24 pm
	Fage 1 of 1
T	s Stamp & File Numbe
4. Lot No, Recorded Plat	
3. Fivate Claims	F G H I J K I
2 6 5 5 6 3	3 2 2
I, Steven P. Bye, in a field survey on November 20, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were	9-10-111
the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Land Manag	
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented	
recovered, found as expressed below:	1-22-23-2
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	
10 30 29 2	27 26 29
A Description of original monument and accessories and/or subsequent restoration:	3-34-35-36
L-5: South 1/4 corner of Section 12	
G.L.O. notes: Set 1/4 post at 39.90 chains Sugar 14 N37E 30 lks. Hemlock 16 S72W 31lks. DATE: 17-97	90 NTY
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	Offen
L-5: South 1/4 corner of Section 12	
1944 Brehmer set iron bar 1974 Weinert found iron bar (Brehmer)	line extending North
Brehmer witnesses: Double elm S25°50'E 29.00' 16" maple S46°00'E 36.10' 1992 Walker found iron bar (Brehmer) on centerline road and fencel Walker witnesses: power pole N17°W 33.17' 12" poplar S25°E 51.48'	S18°W 41.70°
Brehmer witnesses: Double elm \$25°50'E 29.00' 16" maple \$46°00'E 36.10' 18" maple \$N54°00'E 41.80' 18" maple \$1000 Miles (Brehmer) on centerline road and fencel Walker witnesses: power pole N17°W 33.17' 12" poplar \$25°E 51.48' 8" cherry \$24°E 39.18' 12" maple \$1996 O'Non found iron (Brehmer)	S18°W 41.70'
Brehmer witnesses: Double elm \$25°50'E 29.00' 16" maple \$46°00'E 36.10' 18" maple \$N54°00'E 41.80' 18" maple \$1000 Miles (Brehmer) on centerline road and fencel Walker witnesses: power pole N17°W 33.17' 12" poplar \$25°E 51.48' 8" cherry \$24°E 39.18' 12" maple \$1996 O'Non found iron (Brehmer)	unty Ig
Brehmer witnesses: Double elm \$25°50'E 29.00' 16" maple \$46°00'E 36.10' 18" maple \$N54°00'E 41.80' Description of monument for corner and accessories established to perpetuate locating the position of the corner: L-5: South 1/4 corner of Section 12 Iron bar accepted as a careful and faithful reestablishment of the position of the original corner by the Leelanau Cou Remonumentation Peer Review Group on November 17, 1997 and replaced with a 3/4" galvanized iron pipe 3' long the position of centerline road and fencel Walker witnesses: power pole N17°W 33.17' 12" poplar \$25°E 51.48' 8" cherry \$24°E 39.18' 12" maple \$1998 O'Non found iron (Brehmer) 1998 O'Non found iron (Brehmer)	STEVEN P. BYE LAND
Brehmer witnesses: Double elm \$25°50′E 29.00′ 16″ maple \$46°00′E 36.10′ 18″ maple N54°00′E 41.80′ Description of monument for corner and accessories established to perpetuate locating the position of the corner. L-5: South 1/4 corner of Section 12 Iron bar accepted as a careful and faithful reestablishment of the position of the original corner by the Leelanau Cou Remonumentation Peer Review Group on November 17, 1997 and replaced with a 3/4″ galvanized iron pipe 3′ lon with a brass cap in a protective monument box. Existing Witnesses: 8″ cherry \$24°E 39.18′ New Witnesses: 8″ cherry \$24°E 39.18′	STEVEN P.