1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN	X.
COUNTY OF LEELANAL	Į
RECEIVED FOR RECORD)

1993 DEC 28 PM 4: 2	1993	DEC	28	PM	4:	2
---------------------	------	-----	----	----	----	---

E۵	or corners in	Filin	ng Require	ment of Act 74, N	Aich. P.A. 197	0	•	0		7.	٠,٠			
	Leelanau (County)	Located Ir););	Corner Code ≠	4	•	Z	Saul REGIST	CER O	ンプ)F DE	\$€¢ EDS	之		
1.	Public Land Survey	т <u>30N</u> т	R	G-13				FIL	E#:	327				
2.	Property Controlling in Section	T T S T S T	R R			-	LI	BER 2	PA	GE 2	24			
3.	Miscellaneous	S T			R	eaiste	r of E	eeds	Stam	n & 1	File	Nun	ıber	
	Property in Sec.	\$ T	R											
4.	Lot No,	Recorded Plat												
	Private Claims					- , เ	A B	Ç D	E F	G	H -	1 J	K	L N
						_ 2	<u> </u>	┿╌	-4	+	· § —	├	-	
						3			$+\!\!+\!\!\!+$		┼	\sqcup	-	<u> </u>
						4	 	 	- -		10—	<u> </u>		-12
١, ـ	Steven P. Bye	$_{-}$, in a field survey on	_Decembe	r 17,	19 <u>93 </u>	5		11	11			\sqcup		
do	hereby certify that under r lines 1 and 2 above were	equirements of P.A. 74, M	ichigan P.A. o	f1970, the corner poin	its mentioned	6	 18	17	 		 -15	L14		-13
CU	rrent manual of survey ins	tructions of the United Si	julations alto tates Departn	rules ineretore as re sent of the Interior Bi	reau of Land	7		LÏ.		上	Ĭ.			<u> </u>
Ma	anagement or by a decree o	of a Court of Law and/or th	at the corner	ni benoitnem atnioq	nes 3, 4 and 5	- 8				$oxed{\mathbb{L}}$	22_			
	ove were in conformance					9	ĺ	1				[]	,—	
	ourt of Law; established, pressed below:	re-established, monum	ented, re-mo	onumented, recovere	ed, found as	10				\top	T	П		\top
						Ţ	30 	29-	28	_	27	26	-	-25 1
M	OTE: Not more than 4 on this certificat		ne town and	I range, may be rec	corded	11			++	+	+-		+	+
	on this certificat	e.				12	3'1	32-	-33	 -	34	-35		-36
Α.	Description of origina	I monument and acces	ssories and/	or subsequent rest	oration:	13 L		 	1 1	-			L_	
	G-13: SE corner,		G.L.O.	"Set post cor 2 - N 49 E, 3	ner to sec	tions	s 33	& 34	4"					
				0 - N 20 W, 1										
			4											

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13: SE corner, Section 33:

1/2" iron rod with cap #13026 (Batzer Jr.), this corner has previously been recorded in file #77 of Land Corners. 5/8" iron rod with cap #19846 (Wernert) found, N 10 E, 1.09' from Batzer corner, and has been recorded in file #216 of Land Corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13: SE corner, Section 33:

1/2" iron rod with cap #13026 accepted by the Leelanau County Remonumentation Peer Group, december 9, 1993, and replaced with a 3/4" i.d. galvanized iron pipe 3' long, with a brass cap.

Power pole - N 55 W, 9.11' 9" Maple - S 76 E, 91.46' 12" Maple - S 64 E, 80.51' Iron rod with cap #19846 - N 10 E, 1.09' 7" Ash - S 40 W, 49.40'

Signed by

Surveyor's Michigan License No.

BYE AND SURVEYOR

OF MI

REVISED MAY 14, 1975 REVISED JAN., 1983