

MAY 1 6 1997

COMMITTER

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 132

For corr	ners in				
_Lenav	vee	Located In:	Corner Code #		
	(County)		•	STATE OF MICHIGAN	
1. Publ	lic Land Survey			LILED	
			· · · · · · · · · · · · · · · · · · ·	13 NOV 96 9:06 A.M.	
		STATE OF HICH. LENAME COUNTY T - 5-S R - 1-E T R T R T R T R S T R S T R S T R Register of Deeds Stamp of Fi A B C D E F G H A B C D E S	10 NOV 70. 7-VO REIIS		
2. Prop	erty Controlling S			JEANETTE D. KNOX	
3. Misc	cellaneous			Tregister of Deeds Starrip & File Number	
Prop	perty in Sec S	TR			
				ABCDEFGHIJKLM	
5. Priva	ate Claims				
	•				
current manual of survey instructions of the United States Department of the Interior Burgay of Land					
				45 . <u>.</u>	
expressed below:		and an analysis of the state of			
NOTE					
NOTE:	Not more than 4 corners on this certificate.	s, all in the same town ai	nd range, may be recorded	13	
	on this certificate.				
A. De	escription of original mon	ument and accessories a	nd/or subsequent restoration:		
	G.L.O. 1824 Robert Clark set post 293 lks W. of post Corner Sec. 4 & 5 Hickory 10 N 50 W 103, B. Oak 18 S 85 E 43 Farly 1900 LL Bishard record called for "Iron, bricks & stone" corner of house S 42, 47 W 97				
	July 1927, Harold Clegg surveyed Cement City Hwy. and the P.O.E. calls for Section corner (no description of				
	monument).			•	
current r Manager above w Court or expresse					
			e tenawee county Road Com	mission and set a small poat spike in the	
			led it in L. 1. P. 435.		
B. De	Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	August 9 4004 Eveny	ated 6' EJW by Z' N S on	on with back has Found ha	ttom of iron pipe at surface was inside o	
	1" X 12" iron pipe 2' d		ta widi back fide. Foully bu	ctom of from pipe at surface was fisher of	
	Also found 3/4" X 18"	pointed iron bar 1'± E		t. Didn't find any trace of a stone or brid	
				re-monumentation corners which fell 1.	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 17, 1996, Replaced the iron pipe I set 8-10-94 with a 3/4" X 3' gas pipe in a monument box.

3/4" X 3' gas pipe capped G.E.R. P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner, which is 1.23 South of the corner recorded in L. 1, P. 435. ME OF MICHIGE

Dbl. hd. nail & disc in Elec. pole N 80° W 157.59

Dbl. hd. nail & disc in Elec. pole N 30° E 26.08

South of corner I had recorded in L. 1, P. 435.

SE. corner at jog in South side of Church N 65° E 145.52

NW. corner of concrete block building S 35° E 69.45

E-13, T4S-R1E, Standard Jackson Co. Re-monumentation monument in monument

box East 193,20

Glenn & Richard Date 7-16-96 Ratified by Peer Group in accordance with P.A. 345

chard Date 10-11-96 Signed by Glenn E. Richard

Surveyor's Michigan License No. 13040

GLENN E

RICHARD

No. 13040