NOV 07 1994

Filed under Remonumentation Act 345 of 1990

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 22

For corners in	•				n <sub>), (1</sub>
Lenawee	Located In:	Corner Code #	1	FIFT	اا ما∠
(County)	·			FLED	10,0
Public Land Survey	T <u>-5-S</u> R <u>-4-E</u>	<u>B-13</u>		OCT 28 1994	•
	T R T R			LENAWEE COUNTY JEANETTE D. KNOX	
	T R			REGISTER OF DEEDS	
	S R				
	S T R	<del></del>	Register of	Deeds Stamp & Fi	le Number
	S T R	·····	<u> </u>		
Property in Sec.	S T R		АВ	CDEFGH	IJKLM
			1 .		
			2 ├─\$	- -5- -4- -3-	-2- -1-
5. Private Claims			—— 3 <del>   </del>	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
			4 7	8 9 10	11 12
. Clann F Diaband	for a grant	Contombor 06 40	5   18 3 9 1 6   18	17 16 15	14 13
i, Glenn E. Richard	, in a field	i survey on <u>September 26</u> 19 n P.A. of 1970, the corner points me	, <u>, , , , , , , , , , , , , , , , , , </u>		
in lines 1 and 2 above were	e in conformance with regulation	ns and rules therefore as required epartment of the Interior, Bureau of	in the 8 19	20 21 22	23 24
		corner points mentioned in lines 3,			
above were in conformance v	with the rules of the Michigan Bo	oard of Land Surveyors or by a Dec re-monumented, recovered, for	cree of a 10 30	<del>  29   28   2</del> 7-	26 25
expressed below:	, re-established, monumented,	, re-monamented, recovered, loc	und as 11 12 31	32 33 34	35 36
NOTE: Not were then A	savere all in the same town	n and range may be recorded	13	92 90 97	
on this certificate		n and range, may be recorded			
A. Description of origin	ial monument and accessorie	es and/or subsequent restoration	on:		

G.L.O. June 1819, Joseph Fletcher set 1/4 post Poplar 6 N 29 E 20, Poplar 3 N 8 W 21 July 1852, Section 31, T5S-R4E was subdivided as shown on survey in Satterthwaite record book but the monument was not described.

Werner Sommer re-established it by setting an iron pipe in the pavement on a line between the NE corner Section 6, T6S-R4E and Southwest corner Section 31, T5S-R4E and the extension of the line between the North 1/4 corner and the occupied Center of Section 31, T5S-R4E and recorded in L. 4, P. 251 on August 17, 1979.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: R.

11-9-93, All trace of the monument was destroyed during road re-construction two years ago when the roadway was excavated 2'+

12-13-93 Set P.K. nail in pavement by retracing surveys done in Section 31, T5S-R4E and Section 6, T6S-R4E. October 6, 1994, removed P.K. nail and set 3/4" X 4' iron pipe capped G.E.R., P.S. 13040 in monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 4' iron pipe capped G.E.R., P.S. 13040 in monument box and is accepted as the best available evidence of the MULLINA position of the original corner. MICHIG

Dbl. hd. nail & disc in Elec. pole \$ 15° E 228.02 NW corner of metal siding on Pole barn S 75° E 252.68 SE corner of conc. block house foundation N 65° W 206.17 SW corner of conc. wall (silage pit) N 75° E 283.97

N 1/4 corner Sec 6, T6S-R4E West 321.01

Surveyor's Michigan License No. 13040

ESSYONAL Co. Rep. Man E. Richard Date September 29, 1994 Ratified by Peer Group in accordance with P.A. 345 Glenn & Ruchard \_ Date <u>Oc+ 19, 1994</u> Signed by Glenn E. Richard

GLENN E.

RICHARD No. 13040