GURVEY & REMONUMENTATION

Filed under Remonumentation Act 345 of 1990

NOV 07 1994

expressed below:

## LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 23

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

CA KANAA KANAA			
For corners in Lenawee	Located In:	Corner Code #	FILED OF A
(County)  1. Public Land Survey	T <u>-5-\$</u> R <u>-4-E</u> TR		LENAWEE COUNTY
in Section S	TR TR TR TR		JEANETTE D. KNOX REGISTER OF DEEDS egister of Deeds Stamp & File Number
Property in Sec. S	T R ded Plat		A B C D E F G H I J K L N
5. Private Claims			3 4 7 8 9 10 11 12 5
do hereby certify that under requir n lines 1 and 2 above were in c	rements of P.A. 74, Michigan F conformance with regulations	survey on <u>September 26</u> 19 94_, P.A. of 1970, the corner points mentioned and rules therefore as required in the partment of the Interior Burgay of Land	7

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. June 1819, Joseph Fletcher set corner post W Oak 16 N 18 E 27, Ironwood 9 S 70 E 12.

March 1882, James Blair couldn't find the corner and set stake and pieces of brick 5.44 ch East of the NE corner of Sec 6, T6S-R4E.

10

11

12

J.L. Richard records from early 1900's called for stake and bricks.

October 1971, Werner Sommer re-established the corner with an iron pipe in the pavement in line of fence North and on line between the Northwest corner and North 1/4 corner of Section 5, T5S-R4E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

11-9-93, All trace of the monument was destroyed during road re-construction two years ago when the roadway was excavated 2'+.

12-13-93 Set P.K. nail in pavement by retracing surveys done in Sections 31& 32, T5S-R4E and Sections 5 & 6, T6S-R4E. October 6, 1994, Removed P.K. nail and set 3/4" X 4' iron pipe capped G.E.R., P.S. 13040 in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 4" iron pipe capped G.E. R., P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl. hd. nail & disc in 36" stump North 110.80

Fd. dbl. hd. nail & disc in Tel. pole S 80° E 204.28

Fd. dbl. hd. nail & disc in 36" stump North 110.80 Fd. dbl. hd. nail & disc in Tel. pole S 80° E 204.28 NE corner of house foundation S 45° E 114.79 NW corner of garage foundation S 20° E 117.93 NE corner of house foundation N 50° W 173.75 NE corner of Tel. pedestal S 65° W 133.12

CONTROL OF SERVICE PRINCE OF THE PROPERTY OF SERVICE CONTROL

Surveyor's Michigan License No. 13040

NE corner Sec. 6, T6S-R4E, West 379.21

Ratified by Peer Group in accordance with P.A. 345

Signed by Henn Chukand Date September 29, 1994

Clenn E. Richard Date Oct. 19,1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

GLENN E.

RICHARD