## REMONUMENTATION

APR 2 8 1995

## Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

001 PAGE 58

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in  |  |  | HILED am  |
|---|--|--|---|
| Lenawee   | Located In:  | Corner Code #  | PM  |
| (County)  |  |  | DEC 05 1994 2101 P.M                              |
| 1. Public Land Survey   | T <u>-5 - S</u> R <u> - 4 - E</u><br>T R<br>T R<br>T R                                     | <u>G-13</u>  | LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS |
| <ol> <li>Property Controlling<br/>in Section</li> <li>Miscellaneous<br/>Property in Sec.</li> </ol> |  | F  | Register of Deeds Stamp & File Number             |
|   |  |  | A B C D E F G H I J K L M                         |
| 4. Lot No.  | Recorded Plat  |  |   |
| 5. Private Claims   | loodidod i lat   |  | 2 6 5 4 3 2 1                                     |
| I, <u>Glenn E. Richard</u><br>do hereby certify that under  | , in a field s   | urvey on <u>September 21</u> 19 94<br>P.A. of 1970, the corner points mentioned  | 4 7 8 9 10 11 12<br>5 6 18 17 16 15 14 13         |
| in lines 1 and 2 above were<br>current manual of survey ins   | e in conformance with regulations<br>structions of the United States Dep                   | and rules therefore as required in the artment of the Interior, Bureau of Lancorner points mentioned in lines 3, 4 and | ne 8 1 <del>9 20 21 22 23 24</del>                |
| above were in conformance   | with the rules of the Michigan Boa   | rd of Land Surveyors or by a Decree of re-monumented, recovered, found as  | a 10 30 29 28 27 26 25                            |
| NOTE: Not more than 4 on this certificate   | corners, all in the same town e.   | and range, may be recorded   | 13  |
| A. Description of origin  | nal monument and accessories   | and/or subsequent restoration:   |   |
| 1957-58, K.L. Suy<br>The corner is sh<br>1958.  | ords, January 31, 1919 " Fou<br>ydam shows a point in his n<br>10wn on Assessor's Plat No. | nd 6.35 East of east rail ".<br>otes 8.70 east of RR. track cente  | in L 14 of plats, Pages 15, 16 and 17, in         |

April 8, 1976, K.L. Suydam recorded the corner in L 3, P 383.

June 2, 1978, found empty monument box after re-construction of road. Dug up pavement using remaining witnesses and found iron pipe 12" deep 1'± Southwest of monument box, set iron pipe in pavement which checked 6.04 to east edge of rail.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

September 21, 1994, Found iron pipe in pavement 6.05 East of east rail. November 16, 1994, Moved monument box to correct location. Found original iron pipe 12" deep. Couldn't remove it so drove it down and set 3/4" X 3' iron pipe capped G.E.R. P.S. 13040 in monument box.

c. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe in monument box capped G.E.R., P.S. 13040 and is accepted as the best available evidence of the position of the original corner.


Dbl. hd. nail & disc in Elec. pole N 70° W 77,69

Dbl. hd. nail & disc in Tel. pole N 10° W 63.86

Dbl. hd. nail & disc in Elec. pole N 75° E 65.96

NW. corner of brick building \$ 30° E 112.07

East edge of east rail West 6.05



| Ratified by Peer Group in accordance with P.A. 345 | Co. Rep. Hun Exchard Date September 29, 1994  Date Nov. 29, 1994 |
|--|--|
| Glenn E. Richard                                   |  |

Surveyor's Michigan License No. 13040

PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971