MAN 2 5 2000

Filed under Remonumentation Act 345 of 1990 LIBER 1 PAGE 314

## LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN LENAVEE COUNTY FILED

SECTION

on this certificate.

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			14	4 JUL 1999 6:3	50:56 PM
Lenawee (County)	Located In:	Corner Code #	}	VICTORIA J. I REGISTER OF	
1. Public Land Survey	T <u>-5-S</u> R <u>-5-E</u> T R T R	G-3		VEDTOICH OL	OCCUD
2. Property Controlling S In Section S					
3. Miscellaneous S Property in Sec	5 T R S T R		Register of Dee	ds Stamp & F	ile Number
4. Lot No, Rec 5. Private Claims	corded Plat		A B C E	DEFGH	I J K L M
			3 4	B   B   10	11 12
do hereby certify that under red in lines 1 and 2 above were in	, in a field s quirements of P.A. 74, Michigan P. a conformance with regulations a	A. of 1970, the corner points ment and rules therefore as required in	oned 6 18 1	17 16 15	14 13
Management or by a decree of a above were in conformance with	ctions of the United States Depa a Court of Law and/or that the corn h the rules of the Michigan Board	ner points mentioned in lines 3, 4 : d of Land Surveyors or by a Decre	and 5 8 19 2	0 21 22	23 24
Court of Law; established, expressed below:	re-established, monumented, re-	e-monumented, recovered, found	las "	9 28 27	26 25

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

- 1819 Joseph Fletcher set post cor. Sec.'s 3, 4, 9 & 10 Hickory 10 S 43 W 11 Lynn 12 S 47 E 22
- 1882 James Blair "Found Corner" and described it as iron bar, stones & brick.
- 1910 J.L. Richard found strap rail and stone
- 1928 Walter Frazier found stake & stones. Added iron pipe
- 1971 AES found boat spike in monument box
- 1972 Kenneth Suydam RLS 17636 found iron pipe? in monument box and recorded it in L 4 P 295
- 1997 I found boat spike in monument box and raised box with adjusting ring
- 1999 Mike Bartolo found boat spike in monument box
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 23, 1999 I found boat spike in monument box and "strap rail" on top of stone 24" deep. Bent the bottom 12" of the 5/8" X 3' re-rod & drove it with the bent bottom on the north side of the stone.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod over stone with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original comer.

Fd 60d spike in 48" Maple S 80° W 128.62 Fd dbl hd nail & disc in 24" pipe S 40° E 76.45 N.W. corner of stone foundation. House #10015 S 35° E 123.67 Cut "X" on concrete foundation of silo N 50° E 118.54



		The state of the s
Ratified by Peer Group in accordance with P.A. 345  Signed by January Dan Glenn E. Richard	Co. Rep Blenn Ruchard	DateJune 22, 1999
	<del>-/-/</del>	
Burveyor's Michigan License No13040		FORM APPROVED BY MICHIGAN STATE BOARD O

ADAPTED FOR WORD PROCESSING MARCH, 1993