OCT 2 1 1997

Filed under Remonumentation Act 345 of 1990

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 197

For corners in	n																	
Lenawee (County)			Locate	d in:		Corn	er Code #					5	IATE (
1. Public Lar	id Survey	T <u>-6-S</u> R <u>-1-E</u> T R			<u>E</u>	G-6				LENAWEE COUNTY FILED								
			TT	R R								9	OCT	97	3:41	P.M.		
2. Property C in Section		s	_ <u>T</u>	_ R _ R									ICTOR:					
3. Miscellane Property is	··· ··	s	. T	_ R					Re	giste	er of	Deed	Sla	ħβ .	₹ F¶	₽ Mu	mbe	31
4. Lot No. 5. Private Cli	aims, R	ecorded I	Plat							1 2 3 4	B	C D	E F	G	H 1	J	K L	. M
I, Glenn E. F do hereby certi in lines 1 and	ify that under in 2 above were	equirement in conform	ts of P.A. nance wi	74, Michig th regulati	gan P.A. (ions and	of 1970, th rules the	refore as r	ints mentior equired in	the	5 6 7	-18-	17		•	15	14-	1	3
current manual Management of above were in Court of Law; expressed below	r by a decree of conformance w established,	a Court of ith the rule	f Law and as of the	d/or that th Michigan	he corner Board of	points me Land Sur	ntioned in li veyors or by	nes 3, 4 and 7 a Decree o	d5 Ia	8 9 10	-19 -30-	20 29	21		27	23 26		4-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						đ	11 12 13	-31-	32	-32	, ;	34	-3 5-	3	6-			

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1815 Thomas Evans set 1/4 Sec. post Buckeye 15 S 44 W 16 1/2 Ash 12 N 84 1/2 E 16 Early 1900's J.L. Richard record "Found corner, tile & crockery"
1919 Walter E. Frazier surveyed Townley Hwy. "Found" Didn't give type of monumentation

1974 Found boat spike. Set I.P. 50' and 100' West (same line)

1988 I set a iron pipe using the two I.P.'s 50' and 100' West

May 1996 I found the iron pipe & took additional witnesses

July 1996 I dug and found bent boat spike 1' deep and at 2' deep a 1/2" galv. pipe leaning to West over stone and another stone 0.5 +/- South. Set 3/4" X 3' gas pipe on west side of stone with top over stone. The road is under re-construction

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 10, 1997 Found iron pipe 1.5 deep and raised with 5/8" X 30" re-rod 7-16-97 Found the re-rod under base course of asphalt and set monument box with top 1 3/4" above pavement to be level with final course of asphalt.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 30" re-rod capped G.E.R. 13040 over 3/4" X 3' iron pipe in monument box and is accepted as the best available evidence of the position of the original corner.

Iron pipe West 49.93

Iron pipe West 99.90

dbl. hd. nail & S.C.S. Benchmark tag in E.P. S 15° W 115.73

dbl. hd. nail & disc in E.P. N 10° W 189.92

dbl. hd. nail & disc in E. P. S 30° E 101.28

ANTE OF MICHIGA **GLENN E** RICHARD No. 13040

	$a.A \qquad a.A$	
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Slenn & Richard Date	September 9, 1997
Ratified by Peer Group in accordance with P.A. 345 Signed by Sound Ruland Da Glenn E. Richard	ate Sent. 19.1997_	
Glenn E. Richard		

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971