

MAY 1 6 1997

COMMISSION

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 121

For corners in			STATE OF MICHIGAN
Lenawee (County)	Located in:	Corner Code #	LENAWEE COUNTY FILED
1. Public Land Survey	T <u>-6-S</u> R <u>-1-E</u> TR TR	<u>C-8</u>	13 NOV 96 9:04 A.M. JEANETTE D. KNOX
Property Controlling     in Section	TR STR		REGISTER OF DEEDS
3. Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number  A B C D E F G H I J K L M
4. Lot No, F 5. Private Claims	Recorded Plat		1 2 6 5 4 7 8 9 10 11 12
do hereby certify that under in lines 1 and 2 above wer current manual of survey ins Management or by a decree above were in conformance Court of Law; established expressed below:	, in a field strequirements of P.A. 74, Michigan re in conformance with regulations structions of the United States Deport a Court of Law and/or that the cwith the rules of the Michigan Boad, re-established, monumented, corners, all in the same town	P.A. of 1970, the corner points and rules therefore as requirement of the Interior, Bureau corner points mentioned in lines and of Land Surveyors or by a I re-monumented, recovered,	9 96, 6 mentioned 7 ired in the 8 u of Land 9 3, 4 and 5 Decree of a 10 found as 11
	nal monument and accessories	and/or subsequent restora	ution:

G.L.O. Oct 1815 Thomas Evans set 1/4 Section post Hickory 6 N 67 W 7 Cherry S 27 W 20 1881 James Blair found large stone Early 1900's J.L. Richard records call for "large stone" 1919 W.E. Frazier surveyed Townley Highway and found stone Nov. 1961 M.D.O.T. found pointed stone and raised with brass plate April 1973 K.L. Suydam found the brass plate and recorded it in Liber 2, Page 403 May 1974 I found the brass plate and recorded it Liber 2, Page 653 Dec. 1975 The Brass plat was torn out. I set short iron pipe from witnesses and recorded it in Liber 3, Page 81.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.

May 19, 1995 The pavement had just been scarified and the iron was gone.

I found the stone and the iron pipes I had set East and July 12, 1996 I found the stone with small drill hole 14" Also a capped (D.E.E. 29245) re-rod 0.2 East. Couldn't restone and set 1/2" X 12" re-rod capped G.E.R. 13040. Set of asphalt. The Lenawee County Road Commission is to	under the 1st course of asphalt pavement. move the stone or re-rod. Drilled 10" into the monument box with top 1 1/2" above the 1st course
C. Description of monument for corner and accessories established	to perpetuate locating the position of the corner:
12" re-rod in top of stone capped G.E.R. 13040 in monusevidence of the postion of the original corner. Iron pipe 2'± South of fence West 50.03 Iron pipe 3.5 ± North of fence East 49.93 The corner is on line between the above two iron pipe Capped (D.E.E. 29245) iron East 32.99 Dbl. hd. nail & Re-mon tag in 30" Wainut \$ 5° W 234.17 Dbl. hd. nail & Re-mon tag in E.P. West 86.11 Face of SW bolt of S. leg of radio tower N 45° E 253.88	GLENN E. RICHARD No. 13040
Ratified by Peer Group in accordance with P.A. 345 Co. Rep.	Date 10-25-96
Glenn E. Richard	
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
	Revised May 14, 1975 Revised Jan., 1983