SURVEY & REMONUMENTATION

JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990 THER 1 PAGE 231

LAND CORNER RECORDATION CERTIFICATE

SECTION

3. Miscellaneous

5. Private Claims

4. Lot No.

Property in Sec

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF KICHIGAN LENAVEE COUNTY

For corners in FILED <u>Lenawee</u> Located In: Corner Code # 22 DEC 97 9:24 A.M. 1. Public Land Survey T-6-S R-3-E VICTORIA J. DANIELS REGISTER OF DEEDS 2. Property Controlling in Section R

Register of Deeds Stamp & File Number

I. Glenn E. Richard	, in a field survey on _December 2, _19_97 ,
do hereby certify that under requirements of P.A. 7-	4, Michigan P.A. of 1970, the corner points mentioned
	regulations and rules therefore as required in the
	States Department of the Interior, Bureau of Land
management or by a decree of a Court of Law and/o	or that the corner points mentioned in lines 3, 4 and 5 ichigan Board of Land Surveyors or by a Decree of a
Count of Law, established, re-established, mo expressed below:	numented, re-monumented, recovered, found as

Recorded Plat

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

4	, , ,	, , ,	- r ·	3 N I	J	
2	-6-	-\$	-	-3-	4	-
3 4		8	-	10	11-	-12
5 6	18-	-17-	- 16	15	-14-	13
7 8	19	20	-21	-22	23-	-24
9 10	30	29	28	27	26	-25
11 12	-31	32	-33	34	36	-36
12						

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824, John M. Mack Set 1/4 Sec. post W. Oak 20 S 25 E 30, Hickory 6 N 34 W 3 1871, Burton Kent described the comer as stone with "X" on top. J.L. Richard record "Stone + on top - 2" gas pipe driven North of stone" 1940's - 1960's, Harold Clegg, R.L.S. No. 13578 owned the property East of this corner. Kenneth Suydam and myself assisted him on surveys he sold out of his property. 1963, I used the stone when I surveyed the boundary for the Plat of Thornhill Terrace, which is recorded in L. 15, P. 18.

1972, Wemer Sommer found the stone and recorded it in L. 1, P. 551

1975, Kenneth Suydam found the stone & iron pipe and recorded it in L. 3, P. 240.

1991 I used the stone for condominium of Fairlawn Manor

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dec. 2, 1997 The iron pipe was gone & the stone was tipped south. I retraced my survey notes from the north of the 1991 Fairlawn Manor condominium and found the stone was tipped 0.50 south. Dug out the stone and set a Harrison monument stamped P.S. 13040 I set the stone 0.8 south of the Harrison monument

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Stone with "X" on top South 0,8

Carsonite post North 0.4'

Survey mark spike & re-mon tag in 24" Oak N 10° E 15.23'

Survey mark spike & re-mon tag in E.P. S 80° E 2.82'

dbl hd nail & re-mon tag in 12" Oak South 21.06'

dbl hd nail & re-mon tag in 8" Pine N 85° W 19.28

Re-rod capped G.E.R. 13040 on section line North 132.61

North edge of asphalt drive South 7.5'

E OF MICHIQ GLENN E. RICHARD No. 13040 PANONAL

u u			A LANGUAGE CO.
Ratified by Peer Group in accordance with P.A. 345	Co. Republish frehand	_Date	December 16, 1997
Signed by Slenn & Rulard De	ate 12-17-97		

Signed by Glenn E. Richard Date /2-/7-9/

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

ADAPTED FOR WORD PROCESSING MARCH, 1993