REMONUNENTATION

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 36

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

NOV 07 1994

For corners in					a an
Lenawee [County]	Located In:	Corner Code #			10:56 pm
1. Public Land Survey	T <u>-6-\$</u> R <u>-3-E</u> TR	<u>L-3</u>		OCT 28 199	4
	TR TR TR TR		Pagister of	LENAWEE COUNT JEANETTE D. MNC REGISTER OF DEE f Deeds Stamp & File	D\$
3. Miscellaneous S	TR			C D E F G H I	
4. Lot No, Recorde 5. Private Claims			1 2 6 3 4 7 5	5 4 3 8 9 10	2 1
i, Glenn E. Richard do hereby certify that under require in lines 1 and 2 above were in co current manual of survey instruction Management or by a decree of a Co above were in conformance with th Court of Law; established, re-e expressed below:	ements of P.A. 74, Michigan I informance with regulations as of the United States Dep ourt of Law and/or that the c ae rules of the Michigan Boa	P.A. of 1970, the corner points me and rules therefore as required partment of the Interior, Bureau o corner points mentioned in lines 3, 4 ard of Land Surveyors or by a Dec	9 94, 6 18 ntioned 7 d in the 8 19 f Land 9 ree of a 10 30 und as 11 12 31) 29 28 27	23 24 26 25 35 36
NOTE: Not more than 4 corne on this certificate.	rs, all in the same town	and range, may be recorded	13	,,,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	

Description of original monument and accessories and/or subsequent restoration:

G.L.O. January 1824, John Mack set 1/4 post Elm 6 S 38 W 3, Hornbean 4 N 75 E 10.

October 14, 1879, G.E. Kedzie, County Surveyor, called for stone.

1907, J.L. Richard records "found old corner under tree" and another record not dated as stone.

July 1948, The notes from a survey for road construction call for "Found near surface" (no description), Concrete

fence post South 30.2, 14" Hickory S about 30° E 36', 16" Elm S about 30° W 33.5

March 1950, W.E. Frazier notes: "This road was graded +" He re-established the corner from the witnesses and the stakes that were set on the road survey and staked a lot on the north side of the road.

November 1971, W. E. Sommer found a p.k. nail in the pavement and the iron pipe set by W.E. Frazier 33' North and recorded in in L. 1, P. 73.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 10, 1994, Found iron pipe in monument box, which checks the witnesses on the L.C. R.C. recorded by W.E. Sommer.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 4' iron pipe capped G.E.R., P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. 60d spike in 18" Hickory S 55° W 41.71 Fd. 60d spike in 18" Hickory N 25° W 42.83 set dbl. hd. nail & disc in Elec. pole North 30.58 Cut "X" on C.M.P. \$ 40° E 24.65 Fd. iron pipe North 33.00



Ratified by Peer Group in accordance with P.A. 345 Signed by Signed by	Co. Rep. Hernt Richard Date October 13, 1994 Date Oct. 20, 1994
Glenn E. Richard	, ,
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUR

VEYORS, JAN. 28, 1971