REMONUMENTATION

NOV 07 1994

4. Lot No. _____, Recorded Plat _

3. Miscellaneous Property in Sec.

expressed below:

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 27

COMMI	SSION Filing Requ	uirement of Act 74, Mich	. P.A. 1970
For corners in Lenawee (County)	Located In:	Corner Code #	PELED 10:56 PM
Public Land Survey	T <u>-6-S</u> R <u>-4-E</u>	_C-1	OCT 28 1994
	T R T R T B		LENAWEE COUNTY JEANETTE D. MNOX REGISTER OF DEEDS
2. Property Controlling in Section	S T R S T R		Register of Deeds Stamp & File Number

5. Private Claims	
	2 -t
, <u>Gienn E. Richard</u>	, in a field survey on <u>September 26</u> 19 94_,
	P.A. 74, Michigan P.A. of 1970, the corner points mentioned with regulations and rules therefore as required in the
	United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law	and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of	the Michigan Board of Land Surveyors or by a Decree of a
Court of Lawr petablished re-established	monumented re-monumented recovered found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO June 1819, Joseph Fletcher set post W. Oak 14 S 33 E 51, W. Oak 20 S 58 W 39 Section 6, T6S-R4E was subdivided in February 1834 as shown on survey in Satterthwaite record book but the monuments are not described.

March 1887, Survey by James Blair states he sighted to the corner but didn't describe the monument.

J.L. Richard records from early 1900's called for stake.

W.E. Frazier set iron pipe in late 1940's or early 1950's from record witnesses.

March 27, 1974 Werner Sommer found spike over iron pipe and recorded the corner in L 2, P 611.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

11-9-93 & 12-13-93, Found 3/4" re-rod in monument box. The road was excavated to a depth of 2'± during construction 2 years ago, and all witnesses destroyed. Retraced surveys done previously and found re-rod in the box to be 0.06 North and 0.17 West of original location. Removed re-rod and set 3/4" X 3' iron pipe capped P.S. 13040, at original location.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the corner.

Found spike in Elec pole N 65° E 131.6 Dbl. hd. nail & disc in Elec pole \$ 50° E 127.2 NE corner of conc step \$ 40° E 94.26 Found 3/8" iron pipe on Section line South 33.01 SE corner Section 31, T5S-R4E East 379.21 NW corner house found. \$ 20° E 91.27

John C'Relaid

Co. Rep. Glenn & Richard Date 9-29-94 Ratified by Peer Group in accordance with P.A. 345

OF MICHIG GLENN E. RICHARD No. 13040

Glenn E. Richard Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971