

OCT 2 1 1997

5

Filed under Remonumentation Act 345 of 1990 IBER 1 PAGE 191

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

For corners in Lenawee	Located In:	Corner Code #	FILED FILED
(County)			9 OCT 97 3:38 P.M.
Public Land Survey	T <u>-6 - S</u> R <u>-4</u> T R T R	<u>L-9</u>	VICTORIA J. DANIELS REGISTER OF TEEDS
2. Property Controlling in Section	S T R		
Miscellaneous     Property in Sec	S T R		Register of Deeds Stamp & File Number

Lot No, Recorded Plat	
Glenn E. Richard	, in a field survey on <u>June 20</u> ,19 97
hereby certify that under requirements of F	A. 74, Michigan P.A. of 1970, the corner points mentioned

do in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 3 4 5 6 7 8 9 10 11 12 13

ABCDEFGHI

JKLM

- Description of original monument and accessories and/or subsequent restoration:
  - G.L.O. June 1819 Joseph Fletcher D.S. set post B. Ash 10 S 87 W 17 Beech 6 N 7 E 39 Oct. 1841 Section 24 & May 1843 Section 25 were subdivided by S.C. Boughton, County Surveyor (monuments
  - were not described) J.L. Richard records from early 1900's called for stone.
  - S.W. corner of house N 50 E 100.8-End post N 30'
  - Oct. 1970 I dug through the pavement and found stone & cedar stake. Raised with iron pipe
  - S.W. corner of house foundation N 55 E 100.88 20" Walnut S 10 E 99.45
  - Sept. 1972 K.L. Suydam found the iron pipe and recorded it in L 2, P 147.
  - June 1993 Road under reconstruction. Found bottom of IP which checked remaining witnesses. Set 3/4" X 2.3 iron pipe in base course of asphalt. Cut off 0.7 of iron pipe as it hit the stone.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 20, 1997 I found the iron pipe as set on June 1, 1993 under the final coat of asphalt and set monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 2.3 iron pipe capped G.E.R. P.S. 13040 in monument box and is accepted as the best available

evidence of the position of the original corner.

SW corner of house foundation N 65° E 100.81

NW corner of house foundation N 55° E 115.73

"X" cut on 15" CMP S 20° E 60.85

"X" cut on 15" CMP S 20° W 61.06

"X" cut on 30" CMP S 45° W 38,99

"X" cut on 30" CMP N 60° W 60.67

spike & disc in 20" Walnut S 10° E 99.45

OF MICHICA GLENN E. RICHARD No. 13040 SPIONAL SI Mail Hay the

5 Co. Rep. Same Ruhard Date September 9, 1997

Date Sept. 19, 1997 Ratified by Peer Group in accordance with 4.A. 345

Glenn E. Richard

Surveyor's Michigan License No. \_13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971