SURVEY & REMONUMENTATION

FEB 1 6 1999

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

SECTION For corners in			LENAUEE COUNTY FILED
_enawee (County)	Located In:	Corner Code #	10 DEC 1998 9:42:40 AM
1. Public Land Survey	T <u>-6-S</u> R <u>-5-E</u> T R T R	C - 10	VICTORIA J. DANIELS REGISTER OF DEEDS
Property-Controlling S in Section S S Miscellaneous S Property in Sec S	T R T R T R T R T R T R T R T R T R T R		Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims	ded Plat		3
I, Glenn E. Richard do hereby certify that under require in lines 1 and 2 above were in co- current manual of survey instruction Management or by a decree of a Co- above were in conformance with the Court of Law; established, re- expressed below:	ements of P.A. 74, Michigan P onformance with regulations of ns of the United States Depa ourt of Law and/or that the cor ne rules of the Michigan Board	and rules therefore as required artment of the Interior, Bureau of mer points mentioned in lines 3, 4 d of Land Surveyors or by a Decre	ntioned in the f Land 7
NOTE: Not more than 4 cor on this certificate.	ners, all in the same tov	vn and range, may be reco	11 12 31 32 33 34 35 36
A STATE OF		andiacoulant conternit	on:

Description of original monument and accessories and/or subsequent restoration

GLO 1819 Joseph Fletcher set 1/4 post Beech 12 N 47 E 20, Beech 18 N 61 E 22 Couldn't find any information on this corner prior to the survey of Blissfield Highway 1919 J.L. Richard survey of Blissfield Hwy. called for the comer, but didn't describe type of monumentation 1975 Roger Meinke & Tim Mohr, under my direction dug and found 3/4" iron rod next to stone & raised to the surface with 60d spike. I recorded it in L. 3, P. 223

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 16, 1998 Found 60d spike over 1" X 30" iron bar on the west side of a small (6" dia.) stone. Had to remove the stone to set a monument box. Replaced the 60d spike and 1" iron bar with 5/8" X 3' re-rod with Lenawee County Remon cap stamped P.S. 13040. The 1" iron bar was leaning South because there is another stone deeper. The bottom of the 5/8" re-rod also leans south with the top bent to be plumb.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with a Lenawee County Remon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

Fd. iron pipe 18" deep on 1/4 line West 33.00 Set re-rod 12" deep on 1/4 line East 33.00 Short steel fence post East 27.2 C-9, T6S-R5E North 2649.69 (Len. Co. Re-mon corner) C-11, T6S-R5E South 2633.91(Len. Co. Re-mon corner)



	Co. Rep. Sterne Reduced Date 11-3-98
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Date 11-3-98
Signed by Sten E Richard Da	to Nov. 11 1998
Gienn F. Richard	ie 1000/03/1/()

Surveyor's Michigan License No. _13040