SURVEY &

REMONUMENTATION Filed under Remonumentation Act 345 of 1990

LIBER 001 PAGE 63

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION For corners in

Lenawee (County)	Located In:	Corner Code #	FILED DEC 29 1994 3: 51 P.M.
1. Public Land Survey	T <u>- 6 - S</u> R <u>- 5 - E</u> T R T R T R	<u>J-11</u>	DEC 29 1994 3. LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous 	STR STR STR	Re	egister of Deeds Stamp & File Number
4. Lot No, I 5. Private Claims			A B C D E F G H I J K L M 1 2 6 5 4 7 8 9 10 11 12
do hereby certify that under in lines 1 and 2 above we current manual of survey in Management or by a decree above were in conformance	requirements of P.A. 74, Michigan F re in conformance with regulations structions of the United States Dep of a Court of Law and/or that the co with the rules of the Michigan Boa	urvey on <u>December 2</u> 19 94, P.A. of 1970, the corner points mentioned and rules therefore as required in the artment of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and 5 rd of Land Surveyors or by a Decree of a re-monumented, recovered, found as	5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9
on this certificat	te.		13

escription of original monument and accessories and/or subsequent restoration:

C.L.O. June 1819, Joseph Fletcher set 1/4 post W. Ash 10 S 60 W 12, B. Ash 6 S 61 E 7. August 1881, James Blair survey "Found the corner" (no description). September 1915, J.L. Richard on survey of the road called for "corner (no description) 3' South of road center line". August 1971, Walter E. Frazier & Associates re-traced the Blair survey and set a 1/2" rod in the pavement. September 1976, I found the "iron rod and recorded it in L. 3, P. 438.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

December 2, 1994, All witness from 1976 recording are gone. I dug through the existing pavement and found the 1/2" iron rod 8" deep in the original pavement. I removed the iron rod and dug through the original pavement and probed for stone but found nothing. The existing road is 3' above the surrounding fields and a new large C.M.P. runs diagonally across the road just west of the corner. Set 3/4" X 3' iron pipe, capped G.E.R., P.S. 13040 in a monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe in monument box capped G.E.R., P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

"X" cut on North end of C.M.P. N 20° E 32.67

"X" cut on South end of C.M.P. S 50° W 28.88

"X" cut on West end of C.M.P. \$ 70° E 39.49

NE. corner of conc. found, of house \$ 70° W 215,25

The corner is in the center of the South lane of the road.



		SONAL MINISTER
Ratified by Peer Group in accordance with P.A. 345 Signed by Alkun C Rufaul	Co. Rep. Alenne Richard Date December 22. Date Dec. 23,1994	<u>1994_</u>
Glenn E. Richard	, Date <u>2007. 30 p. 1. p</u>	
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOAR	RD OF LAND SU

AVEYORS, JAN. 28, 1971