

OCT 1 9 1998 .

Filed under Remonumentation Act 345 of 1990 LIBER 1

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE STATE OF MICHIGAN LENAVEE COUNTY FILED

SECTION

25 SEP 1998 1:15:18 PM

For corners in			
_Lenawee(County)	Located in:	Corner Code #	VICTORIA J. DANIELS
1. Public Land Survey	T <u>-7-S</u> R <u>-3-E</u> TR TR		REGISTER OF DEEDS
2. Property Controlling S	T R T R T R		Register of Deeds Stamp & File Number
4. Lot No, Records 5. Private Claims	ed Plat		3 + + + + + + + + + + + + + + + + + + +
in lines 1 and 2 above were in con current manual of survey instructions Management or by a decree of a Cou above were in conformance with the	formance with regulations s of the United States Depart of Law and/or that the con rules of the Michigan Boar	survey on <u>September 20, 19 98</u> 2.A. of 1970, the corner points mentions and rules therefore as required in the artment of the Interior, Bureau of Larger points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of re-monumented, recovered, found as	he nd 7 15 8 19 20 21 22 23 24 fa as 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corn on this certificate.	ers, all in the same to	wn and range, may be recorded	d 11 32 33 34 35 36 13
A. Description of original mor	nument and accessories	and/or subsequent restoration:	
GLO 1824 John Mu	llett set post on Sec. 2	2, 3, 10 & 11 W. Oak 14" S 6	5 E 16 W. Oak 12 N 55 W 30

Early 1900's J.L. Richard's record Iron & bricks on top of stone

1925 Beecher Road survey called for "R.R. spike=Section corner"

1940± Walter Fraizer set a monument box when the concrete pavement was put in

1974 Iron pipe in monument box recorded by MDOT in L 2 P 621

1981 I found a iron pipe over stone in a monument box & recorded it in L 5 P 40

1997 Donald Bendzinski P.S. 35989 found iron pipe in monument box and recorded it in L 5 P 336

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept. 20, 1998 Found iron pipe (almost rusted away) in concrete in a monument box. Dug out some of the concrete & the iron pipe broke off. Drilled thru the remains of the iron pipe. Hit the stone when driving the re-rod and the rod tipped to the S.W. while driving it down. Bent the top 8"± to be plumb at the location of the found iron pipe.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

"X" cut on south face of steel stop light pole N 20° W 35.18

"X" cut on north face of steel stop light pole S 30° W 51.82

"X" cut on NW bolt in base of AMOCO sign S 65° W 109.84

"X" cut on south bolt in base of flood light pole N 75° W 113.47

OF MICHIGA GLENN E. RICHARD No. 13040 dbyonal sur

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Sunt Fula	Date <u>September 22, 1998</u>
Signed by Sept. 23,1998. Glenn E. Richard Date Sept. 23,1998.	•
Currentede Michigan Licanae No. 12040	EORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUI