

## Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 04

MOIDSHAIDA

NOV 07 1994

	COMMISS				
	corners in nawee (County)	Located In:	Corner Code #	FILED 2:59 P.M.	
1. 1	Public Land Survey	T-7-S R-5-E	<u>J-13</u>	OCT 10 1994	
		T R T R T R		LENAWEE COUNTY JEANETTE OF MOX REGISTER OF DEEDS	
i	n Section	S T R S T R		Register of Deeds Stamp & File Number	
		S T R S T R		ABCDEFGHIJKLM	
4. I	_ot No, R	ecorded Plat		1	
5. 1	Private Claims			3 4 7 8 9 10 11 12	
I, <u>C</u>	Olenn E. Richard	, in a fie	ld survey on <u>August 25</u> 1	9 94 6 18 17 16 15 14 13	
in lin	nes 1 and 2 above were	e in conformance with regulation tructions of the United States I	an P.A. of 1970, the corner points mons and rules therefore as require Department of the Interior, Bureau	ed in the 8 19 20 21 22 23 24 of Land	
abov	e were in conformance	with the rules of the Michigan I	e corner points mentioned in lines 3, Board of Land Surveyors or by a De d, re-monumented, recovered, fo	cree of a 10 30 29 28 27 26 25	
expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded					
	on this certificate	е.			
Α.	A. Description of original monument and accessories and/or subsequent restoration:				
	G.L.O. 1819, Joseph Fletcher set post B. Ash 10 N 28E 24, B Oak 9 S 2 W 9  November 3, 1886, James Blair set stake and tile 98 3/8 links West of N 1/4 post of Section 2 midway between stake a SW corner and stake under a stone at the SE corner of Section 35, T7S-R5E.  The corner monument couldn't be found during a survey of Stadler Road in 1958, and an axle was set at the record jog from the N 1/4 corner of Section 2, T8S-R5E.  March 30, 1976, I found the axle shaft in a monument box and recorded it in L. 3, P. 394.				
В.	Description of corne	er evidence found and/or me	ethod applied in restoring or rec	establishing corner:	
	August 25, 1994, F 3/4" X 3' iron pipe	Found axle shaft in Monu e capped P.S. 13040.	ment box 4" under present	surface of pavement. Replaced the axle with	
c.	·		***	e locating the position of the corner:	
	3/4" X 3' iron pipe in original corner.	i monument box and is a	ccepted as a careful and fail	thful reestablishment of the position of the	
	Dbl. hd. nail & dis Dbl. hd. nail & dis Dbl. hd. nail & dis	on 1/4 line 33.00 and 458 c in square post N 10° E c in Elec. Pole S 65° E 139 c in Elec.Pole S 65° W 223 tion 2, T8S-R5E, East 64.83	38.15 ).99 3.17	GLENN E. RICHARD NO. 13040	
₽ <sub>a</sub> +	ified by Peer Group in	accordance with P.A. 345	Co. Rep. Honne Ru	Date 9-15-94	
	ned by Her Gloup in	& Richard	Date Oct	10,1944	
18		E. Richard			
Sur	veyor's Michigan Lice	nse No. <u>13040</u>		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19	