

Filed under Remonumentation Act 345 of 1990 LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 67

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			EU F
Lenawee	Located in:	Corner Code #	FILED
(County)			MAR 1 4 1995 3:19 PM
1. Public Land Survey	T <u>-8 - \$</u> R <u>- 3 - E</u> T R T R T R	C-5	LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS
2. Property Controlling in Section	S T R S T R		Register of Deeds Stamp & File Number
Miscellaneous Property in Sec.	STR STR		ABCDEFGHIJKLM
4. Lot No, 5. Private Claims	Recorded Plat		2 5 5 4 3 2 1 3 4 5 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
do hereby certify that under in lines 1 and 2 above we current manual of survey in	, in a field s r requirements of P.A. 74, Michigan are in conformance with regulations astructions of the United States Dep	P.A. of 1970, the corner points me and rules therefore as required partment of the Interior, Bureau of	entioned 7 d in the 8 19 20 21 22 23 24 of Land
Management or by a decree	e of a Court of Law and/or that the ce with the rules of the Michigan Board, re-established, monumented,	orner points mentioned in lines 3, ard of Land Surveyors or by a Dec	4 and 5 cree of a 10 30 29 28 27 26 25
NOTE: Not more than 4 on this certifica	4 corners, all in the same town te.	and range, may be recorded	13

Description of original monument and accessories and/or subsequent restoration:

G.L.O. March 1824, John Mullett set post Secs. 7, 8, 17 & 18, W. Oak 60 S 60 E 2, Beech 5 N 60 W 41 May 1871, B. Kent, County Surveyor, surveyed the west half of section 17 with a note "NW corner not found". J. L. Richard, records of the adjoining sections have no information on the corner. Book 1 of surveys at Register of Deed has a survey by J.L. Richard done in 1908 and that shows found stone & stake. Packard road was surveyed in 1940 by Harold Clegg, R.L.S. 13578, but the corner was not found or re-established. August 4, 1969, I set a bolt for the corner using the information from the road survey and proportional measurements from occupation lines north and south. November 28, 1986, I found the bolt under 2" of asphalt and recorded it in L. 5, P. 178.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

September 2, 1994, Found bolt in pavement which checked witnesses. December 12, 1994, Replaced bolt with 3/4" X 3' iron pipe capped P.S. 13040 and installed monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

3/4" X 3' iron pipe capped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

NW Corner of brick house S 35° E 93.55 NE Corner of brick house \$ 40° E 127.82 Dbl. hd. nail & disc. in elec pole N 45° W 34.62



Fd. "X" cut on top of C.B. N 25° E 94.26	No. 13040
	91 and
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Den E Richard Date November 17, 1994
Signed by Glenn & Richard	Date <u>Dec.21, 1994</u>
Glenn E. Richard	
Surveyor's Michigan License No13040	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 1975
	revised Jan., 1983 Adapted for word processing march, 1993