SURVEY & REMONUMENTATION

JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE BER 1 PAGE 226

STATE OF MICHIGAN

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in			LENAWEE COUNTY	
Lenawee (County)	Located In:	Corner Code #	FILED	
Public Land Survey	T <u>-8-S</u> R <u>-3-E</u> TR TR	1-7	5 NOV 97 11:59 A.M. VICTORIA J. DANIELS	
2. Property Controlling S	T R R T R R T R R T R R T R R T R R R R		REGISTER OF DEEDS Register of Deeds Stamp & File Number	*
4. Lot No, Recorde 5. Private Claims	ed Plat		A B C D E F G H I J K L 1 2 5 3 4 7 8 9 10 11 12	
t, Glenn E. Richard do hereby certify that under requirer in lines 1 and 2 above were in concurrent manual of survey instructions Management or by a decree of a Cou above were in conformance with the Court of Law; established, re-est expressed below:	formance with regulations a s of the United States Depa it of Law and/or that the con rules of the Michigan Board	and rules therefore as required in intriment of the Interior, Bureau of oner points mentioned in lines 3, 4 and Surveyors or by a Decre	97. 5 Intioned in the f Land 7 and 5 8 19 20 21 22 23 24	
NOTE: Not more than 4 corn on this certificate.	ers, all in the same tow	vn and range, may be recor	rded 11 32 33 34 35 36	

Description of original monument and accessories and/or subsequent restoration:

1824 John Mullett set post corner Sections 14, 15, 22 & 23 Sugar 12 514 E 24 Beech 8 N 65 W 390 1886 James Blair Searched for corner but couldn't find. Re-established it by proportional distances from 1/4 corners found 1/2 mile N, E, S & W. Set stone pump.

Early 1900's J. L. Richard records same as J. Blair.

1956 M. S. H. D. found iron pipe.

1968 I found 1" steel bar in monument box.

1973 K. L. Suydam recorded the corner as F I P in monument box in Liber 4 Page 115.

1978 K. L. Suydam recorded the corner as FIP in monument box in Liber 4 Page 183.

1991 Mannik & Smith Engineers found "Concrete monument?"

Description of corner evidence found and/or method applled in restoring or reestablishing corner:

Oct. 23, 1997 Found boat spike in monument box. Probed and hit something 2 1/2" deep. Dug but it was small pieces of lime stone. Found traces of brick in the clay. Set 3/4" X 3' iron pipe capped G.E.R. 13040 in location of the boat spike.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Angle iron post in concrete N 20° W 202.23 Fd PK & M.S.H.D. tag in E. P. N 25° E 174.11 "X" cut on top conc. culv. N 65º E 72.57

"X" cut on top conc. culv. S 65° W 72.53

"X" cut on top conc. Hdwl S 65° W 63.15

"X" cut on top conc. Hdwl N 65° W 64.15

glenn e RICHARD No. 13040

• • • • • • • • • • • • • • • • • • • •	9/1 00/1	PR1
Ratified by Peer Group in accordance with P.A. 345	Co. Rep Harre Ruhard Date October 28, 1997	
Signed by Glenne Rulard Da		
Glenn E. Richard		