SURVEY & REMONUMENTATION

AUG 1 0 1998

LAND CORNER RECORDATION CERTIFICATE

PAGE 244

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAWEE COUNTY

For corners in					LENA		LUUNI I			
<u>Lenawee</u>	Located In:	Corner Code #				FILE	4			
(County)					1 JUL	98 ;	3:05 P	'.H.		
Public Land Survey	T <u>-8-S</u> R <u>-4-E</u> T R T R	M-4		VICTORIA J. DANIELS REGISTER OF DEEDS						
2. Property Controlling Sin Section S	TR									
3. Miscellaneous S Property in Sec	S T R		Regis	ster of	Deeds	Stam	p&F	ile N	umbe	∍r_
4 Lot No	orded Diet			А В	CDE	F (GН	1 J	ΚL	. N
5. Private Claims	orded Plat		2		-5	-	3	1	$\overline{\Box}$	— —
I Clans E Dishard			3 4		B	9	10-	111		2
I, Glenn E. Richard , in a field survey on April 8, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				18	17-	6-	15-	14	- 1	3
				19	20	21	22	23	2	4-
expressed below:		Temperature Red Temperat, Tourid	10	0 - 30-	29	28	27	-26	1-2	5
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				1 2 31	32	-33-	34-	35		6-
			13	ა ——						

Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Wampler set 1/4 Sec. post Ash 8 S 43 E 5 Ash 5 N 34 W 17 1873 Webb Jipson reestablished the corner "Prorate." Monumentation type not given 1889 James Blair set stake in the "found old hole 1.25 1/2 chain north of W 1/4 post Riga" 1980 I dug 2' deep and found stone over remains of wood stake. I set iron pipe along east side of stone and recorded it in L 4, P 329 1980± Lenawee Co. Road Commission rebuilt the road and set a monument box at the iron pipe

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

April 8 I found 1/2" X 3' iron pipe in monument box and replaced it with a 5/8" X 3' re-rod with Lenawee Co. Re-mon cap stamped P.S. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

5/8" X 3' re-rod with Lenawee Co. Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd dbl hd nail & disc in E.P. N 20° E 74.38 Fd dbl hd nail & disc in E.P. S 5° E 293.19 steel fence post S 15° E 92.80 Corner of telephone pedestal S 15° E 88.05

A-4 T8S R5E South 82.81



	1345555 28 6
Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Henne Rucks Date June 9, 1998	
Signed by Slenn E. Richard Date 6-26-98 Glenn E. Richard	
Surveyor's Michigan License No. 13040	IBO OF LAND