## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74. MICH. P.A.1970 Luce Co.

	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T45_ N., R8 W.	C-12 B-11	_
2. PROPERTY CONTROLL- ING IN SECTION	N. R. E. W.		_
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. S., R W.		_
4. LOT NO , REC	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in re-established, monumented, re and rules therefore as required Bureau of Land Management o	lines 1 and 2 above were, in a monumented, recovered or in the current manual of sure r by a decree of a court of law vey on	estored as expressed below vey instructions of the Unit v. Furthermore, that the c ., 19, found, recovered Michigan State Board of Re	nts of P.A. 74, Michigan P.A. of 1970, 12-1, 1978, established, and in conformance with regulations ed States Department of the Interior, orner points mentioned in lines 3, 4, restored, established or re-established egistration for Land Surveyors or, by a
	between Sections 31-	32, bearings were:	Hemlock 7", S68°E, 20 lks. and Maple 5", N30°N, 13 lks.
		21 hasrings Werel	Spruce 4", S54°E, 11 1ks. and
B. Description of corner evidence.  C-12 Restored corner	r between two Section	plied in restoring or re-estab n corners, found no	evidence of original corner.
B. Description of corner evidence.  C-J2 Restored corner	ence found and/or method ap	plied in restoring or re-estab n corners, found no	lishing corner: evidence of original corner.
B. Description of corner evidence.  C-12 Restored corner  B-11 Restored corner  C. Description of monument  Placed 1" pipe with 4  C-12 New Bearings:  B-11 New Bearings:  SIGNED BYBILLY D. Busuleyers MICHIGAN 19	for corner and accessories estable	plied in restoring or re-estable corners, found no asure between two Seablished to perpetuate location corners.  48.1' and 8" Cedar, W, 11.6'.	evidence of original corner.  ection corners.  Ing the position of the corner:  N60°E, 48.6' and  N28°W, 30.2'.
B. Description of corner evidence. C. 12 Restored corner B.11 Restored 1° pipe with 4° C.12 New Bearings:  B.11 New Bearings:  SIGNED BY BILLY D. BU SURVEYOR'S MICHIGAN INFOR STATE AND UNITED SIGNED BY	for corner and accessories estimated accessories e	plied in restoring or re-estable corners, found no asure between two Seablished to perpetuate location corners.  48.1' and 8" Cedar, W, 11.6'.  7.5' and 5" Cedar, DATE 2	evidence of original corner.  ection corners.  Ing the position of the corner:  N60°E, 48.6' and  N28°W, 30.2'.  BILLY D BUCKLER COF MICHER SURVEYOR CONTROL OF THE OF OF

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971