LAND CORNER RECORDATION CERTIFICATE

	Filing Requiremen			
or corners in				
Luce	Located In:	Corner Code #		
(County)	Located III.	comer code #		
Dublic Land Comme	T /20 B 49		·	
. Public Land Survey	T_45N_R_8M	<u> </u>	:	
	TR			
	R			
Droporty Cantualling	S R			
Property Controlling	S I R		•	
Section Miscellaneous	5 I R		_	
Property in Sec.	5 !K		Reg. Num	Ister of Deeds Stamp & File
Property in Sec.	S TR	-		
Lot No, Rec	orded Plat		ABCI	EFGHIJKL
Private Claims	orded reat		2 - 6	<u></u>
THE COUNTY			3	
Otanhan I Osmanlanki	Jun 25	5 2003	4	
Stephan J. Szyszkoski	, in a field survey on	, 20 do hereby	state	
at under requirements of P.A	. 74, Michigan P.A. of 1970, the co	orner points mentioned in lines 1	and 2 1	
ove were in conformance wi	th regulations and rules therefore	e as required in the current man	ual of 6 18 -1	7-1-16-15-1-14-13-
vey instructions of the United cree of a Court of Law and a	d States Department of the Interio For that the comer points mention	or, Bureau of Land Management o	r by a 7	┝╼╄╼┼╼┼╼┼╼┼
formance with the rules of	the Michigan Board of Land Survey	evors or by a Decree of a Court of	ere in 8 19 2	0 21 22 23 24
ablished, re-established, mo	numented, recovered, found as ex	xpressed below:	9	
NTF: Not (1 - 0			10-302	9 29 27 26 28
TE: Not more than 2 on this certificate.	corners, all in the same town	and range, may be recorded		
on this certificate.	•		11 1	
Description of original of	nonument and accessories and	d/or subsequent restaration.	12 -31 3	2-1-33-1-34-1-35-1-36-
			13	2680.00 Set post. Fir 10
remains of the original (Cedar Line Tree by Billy D. B LCRC L1 PBB Luce County Reco	Buckler. Set 1° iron pipe wi ord <u>s</u>).	oup.	
remains of the original (Cedar Line Tree by Billy D. B LCRC L1 P88 Luce County Reco	Buckler. Set 1° iron pipe wi ords).	oup.	
Hemlock S74W 23.6' (ref.	LCRC L1 P88 Luce County Reco	ords).		
Hemlock \$74M 23.6' (ref.	LCRC L1 P88 Luce County Reco	ords). I applied in restoring or reesta	ablishing corner:	
remains of the original of Hemlock \$74M 23.6' (ref. Description of corner example to the original post and according to the original of the	LCRC L1 P88 Luce County Reco vidence found and/or method	ords). I applied in restoring or reestals. Recovered the 1972 monume	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original post and accance from the 1972 witness	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original of corner end and an original post and accance from the 1972 witness	LCRC L1 P88 Luce County Reco vidence found and/or method	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original of corner end and an original post and accance from the 1972 witness	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original post and according to the original post and according to the original origin	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original post and accorden the 1972 witness	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original of corner end and an original post and accance from the 1972 witness	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original post and according to the original post and according to the original origin	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the original of the original post and act ance from the 1972 witness	vidence found and/or method ccessories were not recovered sses, both in good condition.	ards). I applied in restoring or reesta I. Recovered the 1972 monume The scribing is visible on	ablishing corner: nt in good condition	n and at record bearing and
remains of the original of the original of the hemlock S74M 23.6' (ref. Description of corner end and an and an and an and an and an	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnesse	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla	n and at record bearing and azes are overgrown on the
Description of corner en The original post and act ance from the 1972 witnes ock. Left the monument in the description of mo	vidence found and/or method coessories were not recovered sses, both in good condition. In place and made new witnesses	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla	n and at record bearing and azes are overgrown on the
Description of corner et ance from the monument in Description of monument in Description of monument in Tound 1 I I pipe with 4	t for corner and accessories es	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla	n and at record bearing and azes are overgrown on the
Description of corner et The original post and ac ance from the 1972 witnes ock. Left the monument in Found 1 I.pipe with 4 cap. Slazed, scribed, a	t for corner and accessories es	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla	n and at record bearing and azes are overgrown on the
Description of corner e The original post and ac ance from the 1972 witnes ock. Left the monument i Found 1 I.pipe with 4 cap. 8lazed, scribed, a	vidence found and/or method coessories were not recovered asses, both in good condition. in place and made new witnesses the for corner and accessories estaluminum and set	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla	n and at record bearing and azes are overgrown on the
Description of corner ending the original of the original post and act ance from the 1972 witnespeck. Left the monument in the original post and act ance from the 1972 witnespeck. Left the monument in the original of the original origina	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnesses the for corner and accessories es aluminum and set	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of t	n and at record bearing and azes are overgrown on the
Description of corner ending the priginal of the original post and act ance from the 1972 witnespeck. Left the monument in the price of the pric	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witness aluminum and set rks plain)	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of the state of th	n and at record bearing and azes are overgrown on the
Description of corner enter the original of the original post and act ance from the 1972 witnestock. Left the monument in the cap. Blazed, scribed, auring nails in: Maple N28E 25.4' (old man healock \$77W 23.95' Maple N24W 16.1' "\$23	vidence found and/or method coessories were not recovered sses, both in good condition. In place and made new witnesses aluminum and set rks plain) "S26" 3 NBT"	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of t STEPHAN J. SZYSZKOSKI LAND	n and at record bearing and azes are overgrown on the
Description of corner ending and ance from the 1972 witnes ock. Left the monument in the new part of the mails in: Maple N28E 25.4' (old marken) maple N28E 25.4' (old marken) maple N28E 35.8' "\$25 Hemlock \$10E 35.85' "\$2	vidence found and/or method coessories were not recovered sses, both in good condition. In place and made new witnesses aluminum and set rks plain) "526" 3 NBT" 5 NBT"	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of the state of th	n and at record bearing and azes are overgrown on the
Description of corner et The original post and act ance from the 1972 witnes ock. Left the monument is cap. 8 lazed, scribed, auring nails in: Maple N28E 25.4' (old man Hemlock S77M 23.95' Maple N24W 16.1' "S23 Hemlock S10E 35.85' "S28 a cedar post adjacent.	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of t STEPHAN J. SZYSZKOSKI LAND SURVEYOR No.	n and at record bearing and azes are overgrown on the
Description of corner end ance from the 1972 witnes ock. Left the monument in the Lagrangian in: Maple M28E 25.4' (old man Hemlock S77W 23.95' Maple M24W 16.1' "S23 Hemlock S10E 35.85' "S25 a cedar post adjacent. Entic. Distances are to result the manument in the manum	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: It in good condition the Maple. The bla ting the position of the surveyor surveyor No. 33986	n and at record bearing and azes are overgrown on the
Description of corner end The original post and action of the monument in Found 1" I.pipe with 4" cap. Blazed, scribed, acting nails in: Maple N28E 25.4' (old man Hemlock S77W 23.95' Maple N24W 16.1' "S23 Hemlock S10E 35.85' "S25 a cedar post adjacent. Enetic. Distances are to reserve the street of the street	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: nt in good condition the Maple. The bla ting the position of t STEPHAN U. SZYSZKOSKI LAND SURVEYOR No. 33986	n and at record bearing and azes are overgrown on the
Description of corner end the mlock \$74W 23.6' (ref. Description of corner end the corner end the 1972 witness lock. Left the monument in the corner end to	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: It in good condition the Maple. The bla ting the position of the surveyor surveyor No. 33986	n and at record bearing and azes are overgrown on the
Description of corner end The original post and actions from the 1972 witnessock. Left the monument is Found 1" I.pipe with 4" acap. Blazed, scribed, acting nails in: Maple N28E 25.4' (old man Hemlock S77M 23.95' Maple N24W 16.1' "S23 Hemlock S10E 35.85' "S25 a cedar post adjacent. Enetic. Distances are to refer the street of the street	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are	applied in restoring or reesta L. Recovered the 1972 monume The scribing is visible on es as described below.	ablishing corner: Int in good condition the Maple. The bla ting the position of the strength	n and at record bearing and azes are overgrown on the
Description of corner ed The original of the original post and actance from the 1972 witnestock. Left the monument is Found 1" I.pipe with 4" R cap. Blazed, scribed, assuring nails in: Maple M28E 25.4' (old mar Hemlock S77M 23.95' Maple M24M 16.1' "S23 Hemlock S10E 35.85' "S28 a cedar post adjacent. Enetic. Distances are to respect to the street of t	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 6 Bearings are mail with	applied in restoring or reestal. Recovered the 1972 monume The scribing is visible on ses as described below.	ablishing corner: It in good condition the Maple. The bla ting the position of the surveyor surveyor No. 33986	n and at record bearing and azes are overgrown on the
Description of corner end ance from the 1972 witnes ock. Left the monument in Found 1" I.pipe with 4" cap. Blazed, scribed, auring nails in: Maple M28E 25.4' (old man Hemlock S77M 23.95' Maple M24M 16.1' "S23 Hemlock S10E 35.85' "S25 a cedar post adjacent. Enetic. Distances are to respect to the state of the state	vidence found and/or method coessories were not recovered sses, both in good condition. in place and made new witnessed aluminum and set rks plain) "526" 3 NBT" 5 NBT" 6 Bearings are mail with	applied in restoring or reestal. Recovered the 1972 monume The scribing is visible on ses as described below.	ablishing corner: Int in good condition the Maple. The bla ting the position of the strength	n and at record bearing and azes are overgrown on the
Description of corner et The original post and act ance from the 1972 witnes ock. Left the monument is cap. Blazed, scribed, auring nails in: Maple M28E 25.4' (old mar Hemlock S77M 23.95' Maple M24W 16.1' "S23 Memlock S10E 35.85' "S28 a cedar post adjacent. Betic. Distances are to make the content of the	vidence found and/or method cressories were not recovered sses, both in good condition. In place and made new witnesses aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are mail with Augustust No. 33986	applied in restoring or reestal. Recovered the 1972 monume. The scribing is visible on ses as described below.	ablishing corner: It in good condition the Maple. The black ting the position of the strength	and at record bearing and azes are overgrown on the he corner:
Description of corner et The original post and act ance from the 1972 witnes ock. Left the monument is cap. Blazed, scribed, auring nails in: Maple M28E 25.4' (old mar Hemlock S77M 23.95' Maple M24W 16.1' "S23 Memlock S10E 35.85' "S28 a cedar post adjacent. Betic. Distances are to make the content of the	vidence found and/or method cressories were not recovered sses, both in good condition. In place and made new witnesses aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are mail with Augustust No. 33986	applied in restoring or reestal. Recovered the 1972 monume. The scribing is visible on ses as described below.	ablishing corner: Int in good condition the Maple. The bla ting the position of the stand stand surveyor STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	and at record bearing and azes are overgrown on the he corner:
Description of corner et The original post and act ance from the 1972 witnes ock. Left the monument is cap. Blazed, scribed, auring nails in: Maple M28E 25.4' (old mar Hemlock S77M 23.95' Maple M24W 16.1' "S23 Memlock S10E 35.85' "S28 a cedar post adjacent. Betic. Distances are to make the content of the	vidence found and/or method cressories were not recovered sses, both in good condition. In place and made new witnesses aluminum and set rks plain) "526" 3 NBT" 5 NBT" 8 Bearings are mail with Augustust No. 33986	applied in restoring or reestal. Recovered the 1972 monume. The scribing is visible on ses as described below.	ablishing corner: Int in good condition the Maple. The bla ting the position of the stand stand surveyor STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	and at record bearing and azes are overgrown on the he corner: