## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich P.A. 1970

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970				
Luce	Located in: Corner Code #				
(County)		i			
1. Public Land Survey	T45N R10N				
Property Controlling in Section     Miscellaneous	TR S TR S TR				
Property in Sec.	s	Register of Deeds Stamp & File Number			
4. Lot No, Reco	rded Plat	— авсрегоніјкі			
		2 - 6 - 5 - 4 - 3 - 2 - 1			
	Sep 29 1997	3			
l. Stephan J. Szyszkoski	, in a field survey on, 19 do hereby sta				
requirements of P.A. 74, Michiga	en P.A. of 1970, the corner points mentioned in lines 1 and 2 a d rules therefore as required in the current menual of survey instr.	above were in _			
United States Department of the that the corner points mentioned	Interior, Bureau of Land Management or by a decree of a Court or I in lines 3, 4 and 5 above were in conformance with the rules of	of Law and for 6 -18 -17 -16 -15 -14 -13			
Board of Land Surveyors or by recovered, found as expressed by	y a Decree of a Court of Law; established, re-established, n slow:	manumented, 8 19 20 21 22 23 24			
NOTE: 11-4					
on this certificate.	ners, all in the same town and range, may be recorded	10 30 29 28 27 26 25			
***************************************		11			
		12 31 32 33 34 35 36			
		13			

A. Description of original monument and accessories and/or subsequent entoration (RB) Buarter corner common to Sections 23-24. Corner established In 1849 by Milliam Ives: "40.00 Set qr. Section post Fir 12 M42E 7, Maple 7 S25M 32". Found no subsequent record of monumentation. In 1975, Michigan Dept. of Natural Resources surveyor Billy D. Buckler traversed line between Sections 23-24 but set no accument at this location. In 1976 and 1977, Sections 24 and 23 were partially subdivided by Buckler. He established this 1/4 corner midway and on a straight line between adjacent section corners and used the position to control the subdivisions. However, this single proportionate position was apparently never monumented during these surveys. In the 1975 field notes, Buckler says he found a "small picket" at 1322' N. of K9 and a "sq. post" at 2645.5' N. of K9. He measured 5262.0' for the whole mile.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(K8) Found no evidence of the original post or accessories. Found but did not accept a 1 1/2" iron pipe at what appears to be the location of the sq. post which Buckler found in 1975 (Meas. 2642.5" M. of K9 to the pipe. The pipe is 1.4" South of Bucklers position prorated over the mile.). Did not recover the small picket 1/4 mile south of here. I believe the pipe is simply a perpetuation by unknown parties of the location of the wood post which Buckler found in 1975. I found no evidence substantiating the location of the post or the pipe as the original corner position. Reestablished the corner on a straight line between section corners 2629.46" Morth and South. At the position for the corner I placed a 1" I.D. x 36" iron pipe capped with a 4" dia. cast aluminum MONR tablet, appropriately stamped. Corner placed and witnessed by T.Stark, Newberry District Office, MONR.

(Fr	Description of	ernos roi tremupom	and accessories established to perpetuate	a locating the position of the corner
100	1 SAC I BYDA	MERIN A LIGHT ARE.		. a v in the late a

Blazed, scribed, and set measuring nails in the following trees:

16" Maple \$74W 8.1' "1/45 MBT"

22" W. Pine S25E 31.9" "1/4S NBT" 10" W. Pine S58E 32.65" "1/4S NBT"

12" Maple N87E 19.55" "1/45 N8T"

1 1/2" pipe North 13.08"

Placed a 3" cedar fence post adjacent.

Trail road is East 10'. Bearings are

magnetic.

Signed by Stephen Smysfast.
Surveyor's Michigan License No. 33986

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Date Nov. 12, 1997

For the Michigan Department of Matural Resources - Forest Management Division