LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	I littlig I todali ett ett ett i 4, tillett. i 20. te														
Luce	Located In:	Cor	ner Code #												
(County)															
1. Public Land Survey	T45 <u>#</u> TF	111	67 E8							٠,					
Property Controlling in Section Miscellaneous Property in Sec.	S TF					Re	giste	r of D	eed	s Sta	amp (ß Fü	e Nu	mbe	er_
4. Lot No, Reco						A	вс	D	E I	F G	н	I	JI	. 1	
5. Private Claims				·	1							7	Ţ		-
		Dot 23	(1995		3	\vdash	<u>"</u>	- 5 - 	Τ.	ោ	— 3- 	\top	2 — 	Ιi	ı —
l, Stephan J. Szyszkoski	in a field expressor			vehv state that unc	_		7	- 6 -			_10-	\perp	T		
requirements of P.A. 74, Michig	jan P.A. of 1970, the co	mer points m	entioned in lines 1	and 2 above were	∖in _			Ĭ.		Ш	Ţ	丄	1_	Ц	_
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,				/or 6 pan _		 B 	-17- 	<u></u>	6	—15- —1	\pm	 	 - 	3—	
Board of Land Surveyors or b recovered, found as expressed b		of Law; est	ablished, re-establ	ished, monumente	Md, ′ B	1	9	20	<u></u>	1_	22-	\downarrow] 23—	_2	4-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				9	1	30	_29_	-	8	 -	士		2	 5	
					1	<u>, </u>	_	_‡_	╙	\sqcup	\perp	\bot	\perp	Ш	_
					13	<u>.</u>	<u>ļ</u> . —	_3 ²	╀₃	3_	3 <mark>4</mark> _	4	 3 ⁵ —	 3	6
					13	,L	Ш	L_				\bot	<u>L</u>		_
A Description of original m (67) Corner common to Sect															

Buckler found iron pipe buried in north edge of road with 2" iron pipe witnesses M45E and S45M, both 45.1" distant. Buckler's M8Ts: 14" Soft Maple \$38E 33.6', 13" Y. Birch N40E 16.2'.

(E8) Quarter corner common to Sections 20-21. Corner recorded in 1979 by Billy D. Buckler, RLS: "Replaced corner from one Cedar stump, a possible bearing tree. Location fits cors. North and South. Placed 1" pipe with 4" aluminum cap, new bearings: 9" Cedar S44E 26.8", 6" W. Spruce M25E 1.6'".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G7) Found 2" iron pipe, buried in north edge of road as described in 1984. Both Buckler's NBTs are in good condition with blazes overgrown. The iron pipe witnesses were found as described above. Re-blazed the MBTs, placed measuring nails with tags in them, and marked two new witnesses as described below. Left the monument in place. This corner is being rerecorded to update the accessories. This area is will be logged in the near future.

(EB) Found and accepted Buckler's monument as described, in good condition, and at record bearing and distance from the N. Spruce MBT. The Cedar NBT was found dead and down. Left the monument in place, marked a new BK blaze and set measuring nail with tag in the spruce, and marked three new bearing trees as described below.

post adjacent. Bearings are magnetic. adjacent. Placed location poster 110' north at E-M trail. Bearings are magnetic.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	
Signed by Stefan J. Surgafiel Date 2- Surveyor's Michigan License No. 33986	1-96	-