

MAR 1 9 1999

SECTION For corners in	LAN Fili	D CORNER RECORD ing Requirement of Ac	OATION CERTIFIC et 74, Mich. P.A. 19	PATE 1970	UUCE CO REGISTE P⊋corde	R OF DEEL	D 3
: Lvce	Located In:	Corner Code #			ber 3		837
(County)	Localed III.	Comer Code #			01-20-1	999 15:0	1:33
1. Public Land Survey	T_45N_R TR TR		, ,		Kathy 9	e <i>Court</i> • Mahar; R OF DEFI	CLF Dep Parinter
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR			Regi	ster of Deed	s Stamp &	File Number
4. Lot No , Record	ded Plat			A 8	CDE	F G H	IJĸĿ
				2 6-		4 3	21
t Stonban I Szüczkocki		Aug 06 1998		3			
I, Stephan J. Szyszkoski, requirements of P.A. 74, Michigan conformance with regulations and r United States Department of the In that the corner points mentioned in Board of Land Surveyors or by a recovered found as appropriate the corner of the state	rules therefore as require terior, Bureau of Land M n lines 3, 4 and 5 above a Decree of a Court o	ed in the current manual of sur Management or by a decree of	1 and 2 above were in rvey instructions of the a Court of Law and /or	4 - 7 - 5 - 18 - 7 18 - 7 18 - 7	17 -1	910	11 12
recovered, found as expressed belo	ow:	•	, and the state of	819_	202	122-	2324-
NOTE: Not more than 2 come on this certificate.	ers, all in the same tow	n and range, may be record	ded	9	+		_ - -
on ans ceruicate.	-			1030	292	827	2625-
				11			
				12 -31-	- 32 3	334	<u> </u>
A. Description of original mont (113) Corner common to Sections sections 34&35. W. Fine 22 N79 24. Corner perpetuated in the four original witnesses in evid bearing N50W 5 lks, S35W 23 lks swamp. Corner monument 1" pipe Record dated 3-27-69.	2-3 T44M-RIIW and E 19, Cedar 12 N50W original position i ence; a W. Pine bea . and S45F 24 Uks	34-35 T45M-REIW. Corne 5." Additional bearing n 1967 by Billy D. Buck. Fring H79E 19 lks, tree l	r established in 189 g trees by Wm. Ives ler, RLS: "This corr broken off about 3'	in 1849: I ner replace high; thre	Jedar 7 8354 ed at an old ee cedar stu	/ 23, Cedar cedar post mps, cut 16	11 5458 t with all 6" high
B. Description of corner evide	nce found and/or me	ethod applied in restoring o	or reestablishing corn	er:			
(II3) Recovered the 1967 monumer in good condition, and at recording the remains have deteriorated at removed to facilitate GPS observat 12.0° from the monument. The monument as a careful and faither described below. Corner recover	nd the scribing is a vations and is now a e discrepancy is pre- ful perpetuation of	no longer visible. Reco a cut stump. The Cedar esumed to be a typograph	the original bearing overed the 1967 Ceda 5", noted in the relical error. This to be a second or the second of the second or the	g trees as r 6" in go cord as be ree has fa	neted in t od conditio ing 120° di llen down.	he 1969 cer n. This tr stant, was	tificate. ee was recovered
C. Description of monument for (I13) Found 1" iron pipe with al MDNR cap. Blazed, scribed, and measuring nails in the following 5" Cedar M25E 13.7' "S35 NBT" 6" Cedar N04W 8.4' "S34 NBT" 6" Cedar S37E 16.9' "S2 NBT" 6" Cedar S55W 19.3' "S3 NBT" Placed 4" squared and scribed ceadjacent. Bearings are magnetic	set dar post	ries established to perpetus of M/C// STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	uate locating the posit	tion of the d	corner:	(11/2. (11/2. (1/2.)	(48)
Signed by tephe.	1. Smowhs	Assistant.	Date 11	lalan			
Surveyor's Michigan License No.	7777		_ Date//	10/18		···	