MAR I S 1999

SECTION

8"

	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970				LUCE COUNTY REGISTER OF DEEMS Pacarded							
Located In: Corner Code #		Ĺ	ber	3 10-19 110	pa 199 L	14:5 LVC	acl	I, D				
1. Public Land Survey						oar: DEE		15 T.	* }*			
2. Property Controlling S T R	F	Regis	ter of	Deed	s Sta	mp &	File	Num	ber			
4. Lot No, Recorded Plat 5. Private Claims	n		c b	E .	F 6	.,		10	,			
5. Private Claims	1	֓֞֞֞֞֜֞֞֜֞֜֞֜֜֜֞֜֜֞֜֜֡֡֡֡֡	ĬĬ	Ť	FG	Н.	I J	K	Ţ			
Oct 12 1998	3 -	-6-				3 			1 - 			
I, Stephan J. Szyszkoski , in a field survey on . 19 do hereby state that under	4	_ _ 7	 		<u>ا</u>		 11		 -12			
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5 -			+	$\vdash \vdash$	\dashv	-	_	4			
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 -	-1 8	17-	 1	6-+	 1,5		-	-13			
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	7	+	1	-		-		+	+			
	8 -	-19 	 20-	2	1—	-22- 	1 23 1	3	-24- 			
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	9	-30	29			77			25			
	11	<u> </u>					1 26		_			
,	12	-31	 32	3	3	 -3 4	35	_	 -36-			
A. Description of original monument and accessories and/or subsequent restoration:	13		<u> </u>	لـــــــــــــــــــــــــــــــــــــ		<u> </u>			-			
side of section 36 (145N RIIN)40.00 set qr. section post. Sugar 16 N55E 28, Birch 16 N26W & 36°. This corner was reestablished in 1979 by Billy D. Buckler. RLS, by the method of sing position was not monumented. Buckler measured 5326.4° between K1 and N1. He used the SPM position 1.	le nr	anart	ionata	mass	Hromo	ant i	hut 11	ho				
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn	er:											
(L13) Original post and accessories not recovered. Found no acceptable evidence of the posit Reestablished the corner by single proportionate measurement to the original record - midway reestablished section corners 2661.66' east and west. The observed mean true bearing of this position for the corner, I placed a 1" ID x 36" iron pipe capped with a 4" dia. cast aluminum Corner placed and witnessed by I.Stark and M.Feldpausch, Newberry District Office.	and o	nal wa∈	ine of	mean a Ao	true	bear '-	ing t	petwe	en			
C. Description of monument for corner and accessories established to perpetuate locating the position of monument for corner and accessories established to perpetuate locating the position of pipe with 4" NONR cap. 81azed, scribed, and set measuring nails in the following: 14" Ironwood N60E 12.4' "1/4S N81" 20" Maple N22E 18.2' "1/4S N81" SZYSZKOSKI LAND 8" Maple S48W 18.4' "1/4S N81" SURVEYOR No. Bearings are magnetic.	tion of	the a	corner		UM	ENTENT EN	からない。					
Signed by Steffer J. Supplies: Date	1/12	198	5									