LUCE COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	riling Re	quitement of Act 14, Mich. P.A	1. 1970	٠
Luce	Located In:	Corner Code #		
(County)	Localed III.	Comer Gode #	Liber Source	
1. Public Land Survey	T46N_R_9W_	D-9	LUCE COUNTY REGISTER OF DEEDS	
1. Fublic Land Quivey	TR		Recorded _	
	<u>TR</u>	· · · · · · · · · · · · · · · · · · ·	Libera Page	657
2. Property Controlling	TR S TR		02-29-1996 15:22:24	Ja L
in Section	S TR		Kathy S. Mahar, Res	aister
3. Miscellaneous	S TR		REGISTER OF DEEDS	4
Property in Sec.	S IR		Register of Deeds Sta	mp & File Number
4. Lot No, Record	ded Plat		ABCDEFG	ніјкі
5. Private Claims	<u></u>		1	
			2 5 5 4	
Keith R. Waters	, in a field survey on $\frac{08/3}{}$	1 19 95 do hereby state that u		_10 _ 11 _ 12
requirements of P.A. 74. Michigan	n P.A. of 1970, the corner poin	ts mentioned in lines 1 and 2 above we	rein	
United States Department of the In-	nterior, Bureau of Land Manage	e current manual of survey instructions o ment or by a decree of a Court of Law an	d/or 6 -18 -17 -16	
that the corner points mentioned	in lines 3, 4 and 5 above were it	n conformance with the rules of the Mich ; established, re-established, monumer	nigan ,	
recovered, found as expressed bel			8 -19 -20 -21	_222324
NOTE: Not more than 2 com	ers, all in the same town and	range, may be recorded	9	
on this certificate.			10 30 29 28	2'72'62'5_
		•	11	
			12 31 - 32 - 33	343536-
A. Description of original mor	nument and concentrics an	dar subsequent restoration:	131	
 D-9 1/4 Corner Common to Sections 20 & 29, Town 46 North, Range 9 West 1850 - Original ties to set post: Maple 10, S74°E 18 links - Hemlock 14, N69°W 27 links. 1975 - Billy D. Buckler, R.L.S. 8887, Luce County recorded corners, page 270. Restored 1/4 corner between two Section corners. Corner lies 6.15' west of a wood post. Witnesses: 8" Spruce, S67°W 12.0' - 8" Red Pine, S68°E 16.0'. Corner lies 6.15' west and 60.85' south of the wood post. 				
•				
B. Description of corner evid	dence found and/or method	applied in restoring or reestablishin	g corner;	
Found a 1" pipe with a DNR and has fallen down. It apper witness corner to the Section Re-established 1/4 corner by	cap as called for in 1975 I ars that the 1" pipe was mi corner C-9, which was 13 single proportionate meas	County Remonumentation Program JCRC. Also found the red pine be stakenly placed on the line between 0 feet south of the Section corner urement on line between Section cound 1" pipe, approximately 26 feet	earing tree, the spruce is dead en the Section corner E-9 and a location. corner E-9 and the correct position	m of COLVERNATION OF THE PROPERTY OF THE PROPE
C. Description of monument	for corner and accessories	established to perpetuate locating t	he position of the corner:	
Corner is a 1/2" rebar with a east-west gravel road (Count 14" Red Pine, S48°E 20.76' 10" Balsam Fir, S04°W 35.4	ry Road 462), 65 feet east o	Remonumentation cap, approxim of the east end of asphalt pavement	nately 26 feet south of the centerl t on said road. Witnesses:	ine of Michiga
7" Spruce, S43°W 34.63'			#	KEITH R.
9" Red Maple, S69°W 18.05			#	WATERS LAND
1" Iron pipe with DNR cap,	5001H 7.3 I/tag P.S. 33142 in the side	of the witness object. Trees are b	plazed and painted.	SURVEYOR
Bearings are compass	s bearings corrected for de	clination.	WE	No. 33142
			W.	SEN CURY
Signed by Ketth R	. Water	Date_	12-29-95	LANU
Surveyor's Michigan License	No. 33142			