## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

Two Corners

1. PUBLIC LAND MERVEY. T. 1.66 % R 11 % K-3  2. PROPERTY CONTROLL. ING IN SECTION. T. S. R. W. S. R. W. S. R. S. R. S. R. W. S. R. S. R. W. S. R. S. R. S. R. W. S. R. S. R. W. S. R. S. R. S. R. S. R. W. S. R. S. R. S. R. W. S. R. S. R. S. R. S. R. S. R. W. S. R. S. R
3. MSCELLANGOLS PROPERTY IN SECTION, T
S. PRIVATE CLAIMS  [REGISTRA OF DEEDS STAMP AND FILING NUMBER  I. Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 8/7 19.72 (established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required as court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 3 above were, in a field survey on 19—, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:  A. Description of original monument and accessories and/or subsequent restoration: Corners placed originally by Francis Coleman, D.S. in 1851.  K-2 Quarter Cor. bet. Sec's. 1-2. Bearings were: W. Pine 20", N46°%, 43 lks. and W. Birch 16", S26°E, 5 lks.  K-3 Section Corner 1-2-11-12. Bearings were: Hemlock 10", N36°E, 17 lks, and Y. Birch 10", S42°W, 30 lks.  5. Description of corner evidence found and/or method applied in restoring or re-establishing corner: K-2 Corner replaced from one probable witness; a W. Pine Stump in proper position. Distance checks to Section Corner ½ mile North.  K-3 Corner re-established by proportionate distance East and West, one mile to Section Corners, and at record distance from ‡ Corner ½ mile North. Found distance East to hill checks.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Placed 1" pipe with 4" aluminium cap at all corners.  K-2 New Bearings: 15" Hemlock, S32°W, 27.8" and 9" Soft Maple, N60°W, 18.1"  Corner lies 33.0" East of road.  K-3 New Bearings: 15" Hemlock, S32°W, 27.8" and 8" Soft Maple, N50°E, 13.8"
5. PRIVATE CLAIMS    Billy D. Buckler
I. Billy D. Buckler do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on
the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on
Corners placed originally by Francis Coleman, D.S. in 1851.  K-2 Quarter Cor. bet. Sec's. 1-2. Bearings were: W. Pine 20", N46°W, 43 lks. and W. Birch 16", S26°E, 5 lks.  K-3 Section Corner 1-2-11-12. Bearings were: Hemlock 10", N36°E, 17 lks. and Y. Birch 10", S42°W, 30 lks.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  K-2 Corner replaced from one probable witness; a W. Pine stump in proper position. Distance checks to Section Corner ½ mile North.  K-3 Corner re-established by proportionate distance East and West, one mile to Section Corners, and at record distance from ½ Corner ½ mile North. Found distance East to hill checks.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners.  K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1'  Corner lies 33.0' East of road.  K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'
W. Birch 16", S26°E, 5 lks.  K-3 Section Corner 1-2-11-12. Bearings were: Hemlock 10", N36°E, 17 lks. and Y. Birch 10", S42°W, 30 lks.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  K-2 Corner replaced from one probable witness; a W. Pine stump in proper position. Distance checks to Section Corner ½ mile North.  K-3 Corner re-establihed by proportionate distance East and West, one mile to Section Corners, and at record distance from ‡ Corner ½ mile North. Found distance East to hill checks.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners.  K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1'  Corner lies 33.0' East of road.  K-3 New Bearings: 15" hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'
<ul> <li>B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:</li> <li>K-2 Corner replaced from one probable witness; a W. Pine stump in proper position. Distance checks to Section Corner ½ mile North.</li> <li>K-3 Corner re-established by proportionate distance East and West, one mile to Section Corners, and at record distance from ½ Corner ½ mile North. Found distance East to hill checks.</li> <li>C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners.</li> <li>K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1' Corner lies 33.0' East of road.</li> <li>K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'</li> </ul>
<ul> <li>K-2 Corner replaced from one probable witness; a W. Pine stump in proper position. Distance checks to Section Corner ½ mile North.</li> <li>K-3 Corner re-established by proportionate distance East and West, one mile to Section Corners, and at record distance from ‡ Corner ½ mile North. Found distance East to hill checks.</li> <li>C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed I" pipe with 4" aluminium cap at all corners.</li> <li>K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1' Corner lies 33.0' East of road.</li> <li>K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'</li> </ul>
Corners, and at record distance from ‡ Corner ½ mile North. Found distance East to hill checks.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed I" pipe with 4" aluminium cap at all corners.  K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1'  Corner lies 33.0' East of road.  K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'
K-2 New Bearings: 15" Hemlock, S32°W, 27.8' and 9" Soft Maple, N60°W, 18.1' Corner lies 33.0' East of road. K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'
Corner lies 33.0' East of road.  K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57°E, 13.8'  EILLY D  BUCKLER
K-3 New Bearings: 15" Hemlock, S80°W, 31.6' and 8" Soft Maple, N57 E, 13.8'  BILLY D  BILLY D  BILLY D
BUCKLER LAND
Lilly & Surfish Surveyor 18
SIGNED BY Billy D. Buckler DATE 8/22/74
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR DATE
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)