LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970 as Amended

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended			
For corners in			1
Luce (County)	_ Located In:	Corner Code #	
(2001.1)			
1. Public Land Survey	T 46N R 11W T R	B5	
2. Property Controlling in Section	S T R S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R	- Contractor	Register of Deeds Stamp & File Number
4. Lot No. , Rec 5. Private Claims	corded Plat		A B C D E F G H I J K L
i, Stephan J. Szyszkoski , in		<u> </u>	3
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6			
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7			
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			9 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corne	ers, all in the same town and rang	e, may be recorded	10 30 29 28 27 26 25
on this certificate.			11 12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (B5) Quarter corner common to Sections 7-18. 1851 Established by Francis Coleman Deputy Surveyor on the Section line between Section corners 40.00 chains east and 41.02 chains west. Set post. Cedar 10" N55E 12 links, Fir 7 S31W 24 links. 1974 Billy D. Buckler RLS reestablished the corner "by extending line thru two Cedar line trees, to East of Corner. Found small stream, 25 links East of corner as record indicates. No evidence of Cedar Witness identified". Set 1" pipe with 4" aluminum cap. 12" Cedar S70W 31.7', 14" Cedar S20E 29.4'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (B5) The original post and accessories were not recovered. Found the 1974 monument in good condition and at record bearing and distance from the 1974 witnesses, both in good condition. Accepted the monument as a careful and faithful reestablishment of the position of the original corner. Distances to adjacent Section corners were found to be 2638.30' to east and 2713.33' to west. The center of a small creek is about 17' east of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B5) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 16" Cedar S17E 30.15' mrkd "1/4S" 1974 NBT 18" Cedar S73W 32.15' do do 14" Cedar NO8W 13.45' mrkd "1/4S NBT" 20" twin Cedar N76E 32.0' do Bearings are magnetic.



Signed by

Surveyor's Michigan License No.

33986

Date

09/25/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities