LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.		One Cort	ner.	
FOR CORNERS OF -:	LOCATED IN -:	CORNER COD	E NUMBER	
1. PUBLIC LAND SURVEY	т. <u>46</u> х, я. <u>12</u>	x. I-11		
2. PROPERTY CONTROLL- ING IN SECTION———	N. S., R	E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION				
4. LOT NO, RECO	ORDED PLAT			
5. PRIVATE CLAIMS			REG	ISTER OF DEEDS STAMP AND
the corner points mentioned in li re-established, monumented, re- and rules therefore as required i Bureau of Land Management or and 5 above were, in a field surve as expressed below and in confor- Decree of a Court of law:	mes 1 and 2 above were, in monumented, recovered or in the current manual of su by a decree of a court of l	n a field survey on_ restored as express rvey instructions of aw. Furthermore, t, 19, found,	sed below and in c the United States hat the corner poin recovered, restored,	, 19 <u>74</u> , established, onformance with regulations Department of the Interior at mentioned in lines 3, 4 established or re-established
A. Description of original monutarial Sec. Cor. 26-27 Bearings were:	ment and accessories and/ -34-35, set by Fra Tamarack 4", N50	ncis Coleman.	D.S. in 1851.	', S49°E, 81 lks.
B. Description of corner evidence I-ll Corner replaced notch and overgr	at wood post. Fou	pplied in restoring o nd North - Wes	or re-establishing cor st witness, a s	ner: stump cut low, with
C. Description of monument for I-ll Placed 1" pipe with New Bearings: 4	r corner and accessories es with 4" aluminium c 4" B. Spruce, S18°	an at corner.		N67°W. 10.21
SIGNED BYBil]	J. D. Buckler Buckler	les.	DATE 8-25-75	BUCKLER LAND SURVEYOR NO 8BB7 LINTSURVEY
SURVEYOR'S MICHIGAN RE				(SEAL)
FOR STATE AND UNITED S	-	error and the second of the second		
SIGNED BY			DATE	
APPROVED AND SIGNED BY		O LAND SUBVEYOR	DATE	
	MICHIGAN REGISTER	ED FUID SHIRE LOK		(GEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.