LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Euce (County)	Located In:	Corner Code #								
1. Public Land Survey	T_46H R_ T_46H R_ T R_ T R_	12W A2								
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_ S TR_			Registe	r of De	eds St	amp 8	File	Numb	ber
4. Lot No, Reco	orded Plat			B C	D E	F 6	; <u>H</u>	1 J	<u>к</u>	L - -
conformance with regulations ar United States Department of the that the corner points mentions	nd rules therefore as require a interior, Bureau of Land M ad in lines 3, 4 and 5 above t by a Decree of a Court of	Aug 24 1995 , 19 do hereby a properts mentioned in lines 1 and 2 d in the current manual of survey insuragement or by a decree of a Court were in conformance with the rules of Law; established, re-established,	tructions of the tof Law and for 6 - of the Michigan	-18	- B 17 20 20	-16	-15-		3	-12-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9 10	_30	-29	28		26	6	-25-
			11- 12-	-31	_32_	_33	34	35	5	-36

A Description of original monument and accessories and/or subsequent restoration:
(Al) Corner common to Townships 46N-47N, Ranges 12N-13N. Corner reestablished by double proportionate measurement in 1956 by Billy D. Buckler. 1" pipe with 4" brass cap. 36" W. Pine stub S56E 242 links, 30" W. Pine stub S05W 188 links.

(A2) Quarter corner common to Section 6 T46M-R12M and Section 1 T46M-R13M. Corner established in 1841 by Mm. A. Burt: 40.00 Set qr. Sec. post, Beech 5 S54E 19, Beech 5 M63M 18.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(Ai) Recovered the 1956 monument as described, in good condition, and at record bearing and distance from the two W. Pine stub witnesses. Left the monument in place and marked four new bearing trees as described below. This corner is being recorded in order to update the accessories.

(A2) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner on a straight line between Section corner 2664.55 ft. south and township corner 2615.93 ft. north, being proportionate to the original record. At the position for the corner, I placed a 1"IOx36" iron pipe capped with a 4" dia. cast aluminum MDMR tablet appropriately stamped. I found a 1/2" re-rod nearby, apparently placed by an adjacent landowner. It's position is noted below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(A1) found 1" iron pipe with 4" brass MI (A2) Set 1" pipe with 4" NONR cap. (A2) Set 1" pipe with 4" MDWR cap. DEPT. OF CONSERVATION cap. Blazed, Blazed, scribed, and set measuring nails scribed, and set measuring nails in the in the following: following: 10" Cherry N20E 33.3" STEPHAN J 4" Aspen S12E 5.4' "S6 NBT" B" W. Pine S73W 23.35' SZYSZKOSKI 10" J. Pine N88N 34.1' "S36 N8T" 5" W. Pine N59W 44.7" LAND 10" J. Pine H15E 24.6" "S31 H8T" 3" Aspen H47E 7.1" "S31 H8T" 6" W. Pine N43N 60.4" SURVEYOR Found 1/2" re-rod \$06# 28.56' Bearings are magnetic. Placed a 5" squared and scribed cedar post adjacent. Bearings are magnetic. CAHDSV CANDELLIC SELECT

For the Michigan Department of Natural Resources - Forest Management Division