	_
	L
-	ъ
- 11	5
≕	_
=	AND
_	
_	_
60	_
_	_
	E 2
77	- 1:
~	
g Requi	~
×	_
_	~
=	
	Z
_	=
-	т
•	
-	-70
-	~
-	-
=	-
œ	~
-	
_	- 1113
_	
	г.
$\mathbf{a}$	7.
=	$\overline{}$
_	•
_	-
ъ	-
-	-
n	
	ъ
-1	
~	_
_	
_	
	÷
•	ᄎ
_	ᅙ
Z	₫
` <b>Z</b>	ğ
<u>`</u>	ᅙ
, <u>≼</u>	ÖZ
, Mic	ONC
, Mich	ONC
Mich.	ON CE
Mich.	ON CE
Mich. F	TON CER
Mich. P	TON CER
Mich. P.	TON CERT
, Mich. P.	TON CERT
, Mich. P.A	TON CERTI
Mich. P.A.	TON CERTIF
Mich. P.A.	TON CERTIF
, Mich. P.A. 1	TON CERTIFIE
, Mich. P.A. 19	TON CERTIFIC
, Mich. P.A. 19	ION CERTIFIC
, Mich. P.A. 197	ION CERTIFICA
, Mich. P.A. 197	ION CERTIFICA
, Mich. P.A. 1970	CORNER RECORDATION CERTIFICAT
Requirement of Act 74, Mich. P.A. 1970	ION CERTIFICATE

Luce    County   Located In:	Filing Requirement of Act 74, Mich. P.A. 1970  47N R 11N	Register of Deeds Stamp & File Number
5. Private Claims    Stephan J. Szyszkoski   in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the comer conformance with regulations and rules therefore as required United States Department of the Interior, Bureau of Land Mai that the corner points mentioned in lines 3, 4 and 5 above with a count of surveyors or by a Decree of a Court of recovered, found as expressed below:	A. Lot No, Recorded Plat  S. Private Claims  Aug 11 2003  Aug	22 - 15 - 1 J K
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	me town and range, may be recorded	30 29 28 2
A. Description of original monument and accessories and/or subsequent restoration: H12) Center of Section 34. Established in 1978 by Billy D. Buckler RLS, at the 9-Sec. 34) East 1/16 corner, Sec. 34. Not established in the original survey.	accessories and/or subsequent restoration: in 1978 by Billy D. Buckler RUS, at the intersection of Not established in the original survey.	n of 1/4 lines.
B. Description of corner evidence found and/or method applied (H12) The 1978 position for this corner is not correct. It was a corner to the 1978 monument and established the proper Center corners, using the corrected position for the Quarter corner south.  [9-Sec. 34] Established the corner midway and on a straight 1 (9-Sec. 34) this date by the undersigned) 1323.12' East.	method ap correct. proper C warter co n a strai.	phied in restoring or reestablishing corner. It was based on an erroneous position for the Quarter corner to the east, II2. enter of Section at the intersection of straight lines connecting opposite 1/4 rner II2. From the corner monumented, the center of a trail is approx. 20'
	es established to perpetuate   Set 1"IDx36" I pipe with 4" cap. Blazed, scribed, and uring nails in: M.Pine N74M 6.7' LPine S77E 12.35' M.Pine N35E 29.9' M.Pine N35E 29.9'	* <del>* * * * * * * * * * * * * * * * * * </del>
NZOE 3.0 CS 56E 9.35' 39E 17.65' 8 magnetic. Distance	M.Pine M35t 29.9 W.Pine S42W 17.6' rings are magnetic. Distanc l with tag. Set cedar post	1200