## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. <u>48 </u> <del>x</del> ., R. <u>8 </u> <del>x</del> .	E-3	
	, T. 48 N. R. 8 V.	10'	
3. MISCELLANEOUS PROPERTY IN SECTION	,T		
4. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS		<del>.</del>	REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, r and rules therefore as required Bureau of Land Management	lines 1 and 2 above were, in a fe-monumented, recovered or rest in the current manual of surveyor by a decree of a court of law.	tored as expressed below and instructions of the United S. Furthermore, that the corne	of P.A. 74, Michigan P.A. of 1970,
			cored, established or re-established ration for Land Surveyors or, by a
A. Description of original mo	nument and accessories and/or su	ibsequent restoration:	
E-3 S.W. Section Con	ener of Section 4. Wood	d Post, OLT'S. Heald Sprud	ck 9, N30 <sup>0</sup> W, 20 lks, e 10, S58 <sup>0</sup> H, 24 lks.
10 South 1/16 corne	er on west side of sect	ion 4.	
B. Description of corner evidence	ence found and/or method applie	d in restoring or re-establishin	g corner:
cedar rost found double the dista	i at the S. 1/16 corner ance between them. A co	on the west section edar rost was found l	n 4 across a squared scribed line of section 4, and ying on the ground near ould not be determined.
10 Corner set at so section 4.	eribed wood post M.P.O.	L. between W. 1/4 cor	ner and S.W. corner of
C. Description of monument:	for corner and accessories establis	shed to perpetuate locating the	position of the corner:
DNR Monument placed a	at both corners. Beari	ngs:	
8" Spruce, S15° 7" Spruce, N41° 8" Spruce, N68° 4" Cedar, S82°	Pw, 7.6' Pe, 29.0'	10 20" Hemlock, 6" Hemlock, 16" Hemlock, 7" Hemlock,	\$44°W, 25.6° N24°W, 22.8° N32°E, 40.6° \$75°E, 22.8°

David 1. Eabbitt

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)