LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. 1 Corner

FOR CORNERS OF -:	LOCATED	IN-:		CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	т48_	^{N.} , R. <u>10</u>	₩.	_D-1
2. PROPERTY CONTROLL- ING IN SECTION	,T	N. S., R	E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	, T	N. S., R	E. W.	
4. LOT NO, RECORDED PLAT				
5. PRIVATE CLAIMS	- 			

REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- D-1 North 1/4 Corner of Section 5. D.N.R. L.S. Billy D. Buckler placed a 1" pipe with Brass Cap on 5-21-52. Bearings: 8" Spruce, N70°W, 30 lks. & 6" Spruce, N20°E, 17 lks.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- D-1 Buckler set this corner from one original B.T. in 1952. Buckler's bearing tree (6" Spruce, N20°E, 17 lks.) was dead and fallen over. Marked new bearing trees.
 - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- D-1 Re-Witt. 1" pipe with Brass Cap. Bearings: 10" W.Pine, $$36^0W , 18.5° 6" Cedar, $$N36^0W , 16.8° 6" Cedar, $$578^\circ$ E, $$33.3^\circ$

8" Spruce N700W, 19.8'

SIGNED BY Light & Wiggins OFFICE

9-19-84

WIGG'NS
LAND
SURVEYOR
NO.
NO.
123521

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521