## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

| LŲ | CE (County)          | Located In: | Corner Code ## |
|----|----------------------|-------------|----------------|
| 1. | Public Land Survey   | T 48N R 10W | <u>E-3</u>     |
| •  |                      | Ť R         |                |
|    |                      | T R         |                |
|    |                      | T R         |                |
| 2. | Property Controlling | S T R       |                |
| -  | in Section           | S T R       |                |
| 2  | Miscellaneous        | s tR_       |                |

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat . 4 Lot No.

5. Private Claims \_\_

Property in Sec.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5. Nov. 13 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Section Corner common to 4-5-8-9. Set by Billy D. Buckler R.L.S. on Aug. 2, 1956. A 1/2" x 36" Steel Bar, 14" H. Maple, N1°E, 40 links and 6" H. Maple, S29°N, 24 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Buckler's steel bar both of his H. Maples have been cut.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed DNR Monument over the steel bar. (Buried), Placed location post on south edge of road.

6" Maple, S84°W, 64.9° 10" Maple, N71°W, 99.6°

10" Maple, N24°W, 86.8'

8" Maple, N26°E, 73.4'

Surveyor's Michigan License No. 23521

PED LAND

WIGGINS LAND SURVEYOR 23521

REVISES MAY 14, 1979