LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Luce Ce. 1 Corner

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
	1. PUBLIC LAND SURVEY	T. 48 N. R. 12 V.	J-7	
	2. PROPERTY CONTROLL- ING IN SECTION—	N, R. E.		
		N., R., E.	1	
	4. LOT NO , REC	CORDED PLAT	· · · · · · · · · · · · · · · · · · ·	
	5. PRIVATE CLAIMS		· · · · · · · · · · · · · · · · · · ·	REGISTER OF DEEDS STAMP AND FILING NUMBER
, J -7	the corner points mentioned in re-established, monumented, re and rules therefore as required Bureau of Land Management of and 5 above were, in a field sur as expressed below and in confi Decree of a Court of law: A. Description of original mon Quarter Corner bet. 5	lines 1 and 2 above were, in a se-monumented, recovered or rein the current manual of surviver by a decree of a court of law vey on, formance with the rules of the nument and accessories and/or 5ec's. 14-23, set by F	field survey on 9-10 estored as expressed below and ey instructions of the United S . Furthermore, that the corner 19, found, recovered, res Michigan State Board of Regist subsequent restoration: Prancis Coleman, D.S.	of P.A. 74, Michigan P.A. of 1970
• •	Cedar 12", N57°W, 3	33 lke. and Fir 10",	\$45° , 42 lks.	
			d	
	B. Description of corner evide	nce found and/or method appl	ied in restoring or re-establishin	ng corner:
J-7	•	e original witness; th	<u> </u>	ng corner: ., in poor cendition.
J-7	Re-placed corner from	e original witness; th	<u> </u>	
J-7	Re-placed corner from	e original witness; th	<u> </u>	
J-7	Re-placed corner from	e original witness; th	<u> </u>	
J-7	Re-placed corner from Feund woed post in pl	e original witness; th	<u> </u>	e., in poor cendition.
-	Re-placed corner from Feund woed post in pl	a original witness; the lace.	e Gedar, N57°W, 33 lk	e., in poor cendition.
Plac	Re-placed corner from Feund woed post in placed. C. Description of monument for the control of	or corner and accessories establishments.	ished to perpetuate locating the	e., in poor cendition. e position of the corner:
	Re-placed corner from Feund woed post in placed. C. Description of monument for the control of	or corner and accessories established accessories established and accessories established established accessories established established established established established established established established establis	ished to perpetuate locating the	e., in poor cendition. e position of the corner:
Plac	Re-placed corner from Feund woed post in placed in place	or corner and accessories established accessories established and accessories established established accessories established established established established established established established established establis	ished to perpetuate locating the	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER
Plac	Re-placed corner from Feund woed post in placed in pipe with 4" Alum New bearings: 10" College College College Billy D. Bugil	or corner and accessories established ar, S72°W, 30.15° adar, N44°E, 15.80°.	ished to perpetuate locating the and 6° Cedar, \$22°E,	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER
Plac	Re-placed corner from Feund woed post in placed in place	or corner and accessories established ar, S72°W, 30.15° adar, N44°E, 15.80°.	ished to perpetuate locating the and 6° Cedar, \$22°E,	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER
Plac	Re-placed corner from Feund woed post in placed in pipe with 4" Alum New bearings: 10" College College College Billy D. Bugil	or corner and accessories established ar, S72°W, 30.15° adar, N44°E, 15.80° at corner.	ished to perpetuate locating the and 6° Cedar, \$22°E,	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER
Plac	Re-placed corner from Feund woed post in placed. C. Description of monument for the second s	or corner and accessories established ar, S72°W, 30.15° adar, N44°E, 15.80° at corner.	ished to perpetuate locating the and 6° Cedar, 822°B,	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER
	Re-placed corner from Found wood post in placed in pipe with 4" Alum New bearings: 10" College Col	or corner and accessories established annium cap at corner. edar, S72°W, 30.15¹ edar, N44°E, 15.80¹. kler egistration no888	ished to perpetuate locating the and 6° Cedar, \$22°B,	position of the corner: 22.05' and BILLY D BUCKLER BUCKLER

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1975