LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

One Corner

		corner code NUMBER 15-A. Sec. 15 Meander cor. on S. si	.de
	EYT. 49	Sec. 15, on Westside Pike Lake	
PROPERTY CONTRO ING IN SECTI	ON ,1		
	ION, T S., R W.		
	, RECORDED PLAT		
PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
ne corner points mentionestablished, monument rules therefore as four eau of Land Managed 5 above were, in a sexpressed below and Decree of a Court of land	oned in lines 1 and 2 above were, in a cented, re-monumented, recovered or required in the current manual of survey gement or by a decree of a court of law field survey on	restored as expressed below and revinstructions of the United St. Furthermore, that the corne, 19, found, recovered, rest. Michigan State Board of Registers are restoration:	I in conformance with regulations States Department of the Interior, or points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
	mer evidence found and/or method ap	attal in vectoring or re-establish	
B. Description of cor 15-A, Sec. 15 R f	ener evidence found and/or method appeared corner from two or acceptain, the tamarack is	iginal bearing trees. laying in water.	ing comer: Cedar is a stub, standing,
f. Description of m	onument for corner and accessories est	laying in water.	the position of the corner:
f. Description of m	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the	ablished to perpetuate locating minium cap at corner.	the position of the corner: Cedar, S72 W, 19.6
f. Description of m	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve	ablished to perpetuate locating minium cap at corner. N55°W, 17.7' and 11' water, 6' from shore erse side.	the position of the corner: Cedar, S72 W, 19.6' BILLY D. BILLY D. BUCKLER LAND SURVEYOR
f. Description of m	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve	ablished to perpetuate locating minium cap at corner. N55°W, 17.7' and 11' water, 6' from shore erse side.	the position of the corner: Cedar, S72 W, 19.6' BILLY D. BILLY D. BUCKLER LAND SURVEYOR
C. Description of m 15_A,Sec.15 SIGNED BY	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve	ablished to perpetuate locating uninium cap at corner. N55°W, 17.7' and 11' water, 6' from shore erse side.	the position of the corner: Cedar, S72 W, 19.6 BILLY D. BUCKLER LAND SURVEYOR NO. NO. NO. NO. NO. NO. NO. N
C. Description of m 15_A,Sec.15 SIGNED BY SURVEYOR'S MIC	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve Billy D. Buckler CHIGAN REGISTRATION NO. 88	ablished to perpetuate locating uninium cap at corner. N55°W, 17.7' and 11' water, 6' from shore erse side.	the position of the corner: Cedar, S72 W, 19.6 BILLY D. BUCKLER LAND SURVEYOR NO. NO. NO. NO. NO. NO. NO. N
C. Description of m 15_A,Sec.15 SIGNED BY SURVEYOR'S MIC	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve Billy D. Buckler CHIGAN REGISTRATION NO. 88 UNITED STATES AGENCIES:	ablished to perpetuate locating aminium cap at corner. N55°W, 17.7' and 11' water, 6' from shore erse side. Checker DATE 8	the position of the corner: Cedar, S72 W, 19.6 BILLY D. BUCKLER LAND SURVEYOR NO. (SEAL)
C. Description of m 15-A,Sec.15 SIGNED BY SURVEYOR'S MICE FOR STATE AND	onument for corner and accessories est Placed 1" pipe with 4" alu New Bearings: 13" Cedar, Corner monument set in the NOTE: See sketch on reve Billy D. Buckler CHICAN REGISTRATION NO. 88 UNITED STATES AGENCIES:	ablished to perpetuate locating uninium cap at corner. N55°W. 17.7' and 11' water. 6' from shore erse side. Checker DATE 8.	the position of the corner: Cedar, S72 W, 19.6 BILLY D. BUCKLER LAND SURVEYOR NO. (SEAL)