LAND CORNER RECORDATION CERTIFICATE L 1970

Fo	r corners in	Filing Requirement of Act 74, Mich. P.A.		
	Luce	Located In:	Corner Code ##	
_	(County)		Some Code 44	
1.	Public Land Survey	T_49X_R_9N_		
		T <u>4911</u> R <u>911</u>		
	•			
	i	T R		
2.	Property Controlling	s T R		
	in Section	S T R	:, 	
3.	Miscellaneous	S T R	_	
	Property in Sec.	S T R	- <u>- L</u>	
4.	Lot No.	, Recorded Plat		
5.	Private Claims			

Register of Deeds Stamp & File Number

I, Stephan J. Szyszkoski , in a field survey on Hay 06, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NQTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(17) Quarter corner common to Sections 13-24. Corner previously recorded by Billy D. Buckler in 1956 as a 1° pipe with a 4° brass cap from the remains of a possible original bearing tree, old squared birch, and wood stake. 1956 MBTs arm: 15" Hemlock M39W 83.5 links. 15" Hemlock S86M 38.5 links. Monument remitnessed in 1961 by Buckler with the following: 12" S. Maple M27M 58 links, 10" S. Maple 874 E 70 links. Found no subsequent record.

(L5) Quarter corner common to Sections 12-13. Corner previously recorded by Silly D. Buckler RLS, in 1976 as a 5/8° iron buried in firelane with the following MBTs: 22' Red Pine S20M 35.8', 15" Red Pine \$77E 50.6'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L7) found and accepted a 1" pipe with 4" brass cap at record bearing and distance from the 1961 MBTs, both in good condition, and at record bearing and distance from the remains of the 1956 NBTs, the Hemlock SN being a stump, and the Hemlock NN being dead. Marked two new witness trees as described below.

(LS) Found and accepted 5/8" iron bar buried at the corner at record bearing and distance from both 1976 M8Ts, which are in good condition. Placed measuring nails with tags in the 1976 mitnesses and took two new MBTs as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L7) Found-1" pipe with 4" brass cap Blazed, scribed, and set measuring nails in the following new bearing trees: 10" Y. Birch N35E 4.05' "1/4S NOT" 10" Healock S10E 18.5" "1/45 HBT" Set measuring nails in the 1961 MBTS: 18° S. Maple N27N 3B.65' 16" S. Maple \$74E 46.85" placed a 5° homiock post adjacent to the monument.

(L5) Found 5/8" iron bar Blazed, scribed, and set measuring nails in the following new bearing trees: 1/45 HBT 3" White Pine SOSE 22.8" 10" Red Pine \$70E 49.9" "1/45 NBT" Set mails/tags in 1976 MBTs: 24° R. Pine S20W 36.65' 18" R. Pine \$77E 51.0"



Surveyor's Michigan License No.