LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Luce	Located in:	Corner Code #					
(County)			ļ				
1. Public Land Survey	TF TF TF	R					
Property Controlling In Section Miscellaneous Property in Sec.	S_10 T_494 F S_10 T_494 F S T F S T F	₹ 104 2		Register	of Deeds St	amp & Fil	le Number
4. Lot No , Reco	rded Plat			A B C	D E F G	I H	JKL
5. Private Claims				1 			
	2	Jun 17 1996) Seo 10 1996		2 6	5 1	3 - 	- 2 - 1 -
. Stephan J. Szyszkoski		n do hereby	state that under	4	8 9	10	-1112
requirements of P & 74 Michic	can P.A. of 1970, the cou	mer points mentioned in lines 1 and 2	2 above were in	5			
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in tines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.				6 -10		15	-1413
				8 19	2021	_22_	-2324-
NOTE: Not more than 2 co	mere at in the same to	own and range, may be recorded		9	 - 		 - - -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				10-30	29-29-	2 7	-2625
				11	+		
				12 31	123'3	34	_3536

A. Description of original monument and accessories and/or subsequent restoration:

[10-Sec. 10] South 1/16 corner between Sections 9-10. Corner not established in the original survey. Found no subsequent record. (2-Sec. 10) East 1/16 corner between Sections 3-10. Corner established in 1971 by Billy D. Buckler, RLS. *Corner placed midway and on line bet. Sec. Cor. to east and 1/4 Cor. to west. Corner lies on North side of E-W firelane. Corner monument: 1° pipe with 4° aluminum cap. Witnesses to corner: 8° A. Pine N14W 12.9', 10° J. Pine 830W 56.6'".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 10) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between 1/4 Corner 1324.12' North and Section corner 1324.12' South. At the position for the corner, I placed a 1'1.0.x35' iron pice capped with a 4° dia, cast aluminum MONR tablet, appropriately stamped. Corner placed and witnessed by T.Stark and D.Lampela, Newberry District Office.

(2-Sec. 10) Recovered The 1971 monument, as described, in good condition, and at record bearing and distance from the Red Pine witness, found in good condition. The J. Pine witness from 1971 was not recovered. Left the monument in place, made new marks at Br on the 1971 A. Pine, and marked three new mitnesses as described below. Corner recovered and remitnesses by T.Stark and D.Lampela, Newberry District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

A THE PARTY OF THE (2) Found 1" pipe with 4" MDNR cap. (10) Set f 'iron pipe with 4" MDNR cas. ALE OF NIC Blazed, scribed, and set measuring nails Blazed, scribed, and set measuring nails in the following: in the following: STEPHAN J 12" R. Pine \$65E 6.55" *\$1/15 BT 12" H, Pine N16W 13.25" "E1/16" SZYSZKOSKI "S1/15 BT" 4" J. Pine \$34W 17.8" "E1/16 8T" 3" Maple N51E 17.1" LAND 4' Macle N27E 24.15' "S1/16 BT" 5" R. Pine N84W 13.55' "E1/16 BT" SURVEYOR 16" R. Pine N15W 82.85" "\$1/16 BT" 12" A. Pine N25E 26.0' "E1/16 BT" Placed a 5° squared and scribed Cedar Placed a 8' squared and scribed cedar post adjacent. Bearings are magnetic. post adjacent. Bearings are magnetic. AND BU