LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in					
Luce	Located In:	Corner Code #			
(County)	Locaceo III.	Corner Code #			
1. Public Land Survey	T 49M R 10M	MC north of I2			
vivianie zana zaniej	T 49N R 10W	12			
	TR				
	S R				
2. Property Controlling in Section	S TR				
3. Miscellaneous	S T R		R	tegister of Deeds Sta	ımp & File
Property in Sec.	S R		N	lumber	
			ABC	DEFGH	IJKLM
4. Lot No, Reco	orded Plat		2 6	4.4	K. 6
J. Fitvate Ctailis	11	8004	3		
, Stephan J. Szyszkoski	Nov 04		4 !	- - - - -	11-12
I,	, in a field survey on 74, Michigan P.A. of 1970, the co	, 20 do hereby	state 5		
above were in conformance wit	th regulations and rules therefore	as required in the current man	ual of 6 18	-17-16-15-	1413
decree of a Court of Law and A	d States Department of the Interior for that the corner points mention	r, Bureau of Land Management o	rbya 7	- - - - -	
conformance with the rules of t	the Michigan Board of Land Survey	ors or by a Decree of a Court of	Law; 8 -19	202122-	-2'32'4
established, re-established, moi	numented, recovered, found as ex	pressed below;	9		
NOTE: Not more than 2 c	orners, all in the same town	and range, may be recorded	10 -30-	-2 9 28 27-	25
on this certificate.			11		
A. Description of original m	nonument and accessories and	/or subsequent restorations	12 -31	32 33 34	3536
witness corner 2.50 chains so I" pipe with 4" brass cap. I (I2) Quarter corner common to jackpine BT bearing N45E 30 lies in N-S fire line. Set I (MC north of I2) The 1957 morn good condition with overging is 494.4' north of I2. To [I2] The 1957 1"pipe with braitness trees, both recovered	ner on the shore of Lake Superputh of the record GLO positions twin Red Pine S32M 61 links of Sections 2-3. 1957 - Recoverinks. BY in good condition. The position is the position of the corner factor of the position of the position of the position of the corner factor of the position of the corner factor of the position of the position.	on on the extension of the last 10" Red Pine SI3E 103 line ered and recorded by Billy Defound 2" pipe in concrete "Red Pine N71W 69 links, 6" applied in restoring or reestation unented the 1957 position 10.1 west of a straight line alls on a bluff-tree line abound a 2" pipe in a concrete sings visible. Accepted the	ine between I3-I2 ks Buckler RLS: "F set by Marcus Sch Red Pine N59E 44 ablishing corner: for the corner f e produced throug out 200' south of base at record b pipe as the best	Replaced 1/4 corner haff, Reg. Surveyor. I links." Trom the two 1957 BT h I3 and I2 as now the present lake elearing and distance	of I2. Set from one 1/4 Corner s, both found monumented, dge. from the 1957
IDNR cap. Set measuring nail 12" twin R.Pine S36W 40.3' m 14" R.Pine S09E 68.85'	s in: base. Set orkd "WC" * 26" R.Pine do * 12" R.Pine "WC BT" 6" R.Pine S do 12" W.Pine unces are to Bearings an	measuring nails in: N66W 46.0' old blazes * N58E 29.4' mrkd "1/45" * S61W 15.2' mrkd "1/45 NBT"	to	OPBIE	
Signed by	1 Sall			12/20/04	
Surveyor's Michigan License	Vo. 3398	36	Date —	. 2, 20, 07	
		nt of Natural Resources, Offic	ce of Land and Fa	cilities	
		FORM APPRO	VED BY MICHIGAN STATE	BOARD OF PROFESSIONAL SU	JRVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995