LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_		
For	corner	s in

Luce	Located In:	Corner Code #			
(County)	_				
1. Public Land Survey	T 49N R 10W T R	J7			
2. Property Controlling in Section	S T R S T R				
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp &	File Number	
4. Lot No. , Rec 5. Private Claims	corded Plat		A B C D E F G H	I J K L M	
ı, Stephan J. Szyszkoski , ir	n a field survey on 08/06/2	do hereby state	3 1 1 1 1 1 1 1	2 12 12	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6					
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			2 23 24		
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and range	e, may be recorded	10 30 29 28 2 11 12 31 32 33 3	7 26 25 4 35 36	
					

- A. Description of original monument and accessories and/or subsequent restoration:
- (J7) Quarter corner common to Sections 14 and 23. 1854 Established by George Cannon Deputy Surveyor. Mr. Cannon calls for the "old" Qr. corner as describes it as being 40.17 chains S 89d30m W of Section corner thence 40.20 chains S 89d37m W to Section corner. Set post. W.Pine 24" N63E 30 links. Hemlock 10" S48W 10 links. 1952 Remonumented by Dean C. DeLaMater RLS at a position located and perpetuated by Marcus Schaaf, Registered Land Surveyor. Remains of one original B.T. still in place, poor condition. Set 1" pipe with 4" brass cap. 12" Red Pine S87W 27 links, 12" Red Pine N83E 36 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J7) Found the 1952 monument in good condition, set inside a 2"ID iron pipe (Schaaf monument), at record bearing and distance from the 1952 accessories, both in good condition. Accepted same as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J7) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap in 2" ID Iron pipe. Set measuring nail with MDNR tag in the side of: 16" R.Pine N89W 18.35' mrkd "1/4S" 1952 NBT 16" R.Pine N81E 24.05' do do 8" W.Pine N21E 19.0' mrkd "1/4S NBT" 10" R.Pine S12E 19.5' do Bearings are magnetic.



Signed by Stephen Supplies Date 09/23/2008
Surveyor's Michigan License No. 33986