## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #	
(County)	_		
1. Public Land Survey	T 49N R 11W T R T R	E4	
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R R		Register of Deeds Stamp & File Number
4. Lot No. , Re 5. Private Claims	corded Plat		A B C D E F G H I J K L M  1
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the corregulations and rules therefore as re Department of the Interior, Bureau corner points mentioned in lines 3, 4 d of Land Surveyors or by a Dec	do hereby state  ner points mentioned in lines 1 and 2 quired in the current manual of survey of Land Management or by a decree of and 5 above were in conformance with ree of a Court of Law; established	y 5 f 6
NOTE: Not more than 2 corron this certificate.	ners, all in the same town and ra	nge, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Quarter corner common to Sections 8 and 9. 1854 - Record of Geo.H.Cannon, Deputy Surveyor states: SO deg. 4' E between Sections 8 & 9 ...40.11 Quarter Section corner. W.Pine 12" N45W 9 links, W.Pine 10" S37E 16 links...S0 deg. 48'E Corrected from 1/4 cor...80.25 Corner of Sections 8-9-16-17. 1961 -Corner remonumented by Billy D. Buckler RLS: "This corner was replaced as set by Marcus Schaaf, Registered Land Surveyor. Found Iron Pipe in concrete in place with both W.Pine B.T.'s in evidence". Set 1" pipe with 4" brass cap. Witnesses: 12" Red Pine S03E 38 links, 9" W.Pine N35W 113 links. Corner record dated 1/30/1962. Found no other record of the Schaaf survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The 1961 monument was not recovered and is presumed to have been destroyed by prior logging operations in the area. Found the Schaaf pipe in concrete buried at the corner position, in good condition, and at record bearing and distance from the 1961 NBTs. The Red Pine SE is in good condition with overgrown blazes. The W.Pine NW is now a cut stump with measuring notch visible. Found no evidence of the original W.Pine B.T.s. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 2" iron pipe. Placed 5/8"x18" rebar inside the pipe and set a plastic cap stamped "MICH DNR LS 33986" on the rebar. Set measuring nail with MDNR tag in the side of:

19" R.Pine S01W 25.18'

mrkd "1/4S" 1961 NBT

9" W.Pine N31W 63.7'

mrkd "1/4S NBT"

8" R.Pine S70W 29.25'

do do

8" R.Pine S79E 17.08' Bearings are magnetic.

Top of monument is

flush with the ground.

STEPHAN J

SZYSZKOSKI

LAND

JRVEYOR

Surveyor's Michigan License No.

33986

Date

02/17/2009