

# LAND CORNER RECORDATION CERTIFICATE

**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**  
Mackinac Co. Two Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 42 N. E. R. 11 E. W.	C-13 15, Sec. 31
2. PROPERTY CONTROLLING IN SECTION 31 _____	T. 42 N. E. R. 11 E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram--over) were, in a field survey on 4/17 1969, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

C-13 Original Sec. Cor. 31-32, on South boundary of twp, set by John Burt, D.S. in 1845.  
Bearings were:  
Tamarack 10° N 23 Links  
Tamarack 6° S 60 E 15 Links

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

C-13 Corner placed in center of E-W road and midway bet. two fence corners. Found no evidence of original corner.  
  
15, Sec. 31 Corner placed in line with fence to North and 89.0' South of fence corner. Corner lied in road, near North edge.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Buried 1 1/2" x 30" iron pipe in road, at corner.  
C-13 New Bearings:  
9" Cedar N20°W 86.1'  
6" Cedar N22°E 76.0'  
  
15, Sec. 31 New Bearings:  
18" Hard Maple N67°E 72.8'

SIGNED BY Billy D. Buckler DATE 6/27/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:  
SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)