## LAND CO Filing Re

OHNER KE	CONDAI	ION CER	CHIEC	AIL	
equirement	of Act 7	4, Mich.	P.A. 1	1970	

For corners in Mackinac Corner Code ## Located In: 1. Public Land Survey 31 T 42N R 11N 2. Property Controlling 31 T 42N R 11W in Section

3. Miscellaneous

Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No	, Recorded Plat	
----	--------	-----------------	--

4.	LOT NO.	, necolucu rial.	 
E	Private Claims		

June 06, 1995 i. Stephan J. Szyszkoski , in a field survey on \_ do heraby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 31) North 1/16 corner, Section 31. Corner not established in the original survey. Found no subsequent record. (12-Sec. 31) South 1/16 corner, Section 31. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 31) found no evidence of prior manumentation at the corner position. Established the corner midway and on a straight line between monumented Quarter corner 1333.31' North and monumented Center of Section 1333.31' South. At the position for the corner, I placed a 1"IOx36" iron pipe capped with a 4" dia, cast aluminum MDNR tablet, appropriately stamped. (12-Sec. 31) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between monumented Center of Section 1330.52' North and monumented Quarter corner 1330.52' South. At the position for the corner I placed a l"IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. From the corner, an old downed wire fence is about 9' easterly.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5-Sec. 31) Set 1" pipe with 4" MONR cap. Blazed, scribed, and set measuring nails in the following: 14" M. Birch N49E 17.0' "NI/16 BT 14" N. Birch SOBE 17.65' "N1/16 BT" "N1/16 BT" B' Maple S42W 18.9' 8" Maple S77M 31.35" "N1/16 BI" Flaced a 5" squared and scribed cedar post adjacent and a location poster on an B" maple 45.5' south. Bearings are magnetic.

Surveyor's Michigan License No.

(12-Sec. 31) Set 1" pipe with 4" MONR cap. Blazed, scribed, and set measuring nails in the following: 14" Cedar N6BE 3.85' "SI/16 BT "S1/16 BT" 16" Beech S31E 29.3' "SI/16 BT" 6" Maple S44W 20.3' 8" Cedar \$56W 5.1' "\$1/16 BT" Placed an old cedar fence post adjacent. Bearings are magnetic.

STEPHAN J SZYSZKOSKI LAND **SURVEYOR** 

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

For the Michigan Department of Natural Resources - Forest Management Division

REVISED JAN . 1983