	Filing Re		ct 74, Mich. P.A.		•							
For corners in			·									
Mackinac Loca	ted in:	Corner Code #										
(County)												
1. Public Land Survey	T 42N R 11N T 42N R 11N T R	M1 M2										
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	TR TR TR TR				Reg	ister	of Dee	ds Sta	amp & 1	File 1	lumb	ег
A I of No Pecorded Dia	•											
4. Lot No, Recorded Pla 5. Private Claims	L	····	···-	) 1 r	4 В	c	D E	F G	H 1	IJ	к	L M
				2	_ [	_	5	-4-	3	2 -		.1.
•		29 2004		. 3	_		++	-	-			_
I. Stephan J. Szyszkoski , in a fi	ald survey on	, 19 do	hereby state that und	ler 4	— ļ		8	9	10	— i 1-	-	12—
requirements of P.A. 74, Michigan P.A. of conformance with regulations and rules ther United States Department of the Interior, Buthat the corner points mentioned in lines 3, Board of Land Surveyors or by a Decrerecovered, found as expressed below:	refore as required in th ureau of Land Manage , 4 and 5 above were I	e current manual of s ment or by a decree on conformance with t	urvey instructions of to of a Court of Law and a he rules of the Michig	he <sup>5</sup> /or <sub>6</sub> an _	—19 —19		17	-16	-15	14-		13-
NOTE: Not more than 2 comes of in	the come tour and			9								
NOTE: Not more than 2 corners, all in on this certificate.	the same rown and	range, may be reci	orded	10			29	 -28		  26-		25—
				11				Ĭ.				Ĭ_
				12		_	] 32——	-33	34	35.		-36—
A. Description of original monuments (M1) Corner of townships T42-43N, RIGhe found at a fence corner and at recorass cap. 6" Aspen S50M 17 links, 6 (M2) Quarter corner common to Section iron pipe in a N-S fence at record be Cedar S33M 44 links, 9" Cedar S86M 56	-11M. 1958 - Rem ord bearing and d " Aspen N44E 28 1 6 T42N-RIIW and earing and distanc	onumented by 8ill istance from the inks, 7" W.Birch Section 1 T42N-R1	y D. Buckler RtS remains of the Ta N24W 53 links. OW. 1958 - Billy	marack O D. Buck	BT N ler	14W 6 found	links and a	. Set ccepte	1" pig d a 1.2	pe wi 25° d	th 4" ia.	•
B. Description of corner evidence for	and/or method	applied in restoring	g or reestablishing	corner:								
(MI) Recovered the 1958 monument in g the OBT Tamarack were not recovered. fencing running south and west. Left (M2) The 1.25" iron pipe noted in the the 1958 record and at record bearing The probable original BT cedar, noted	The remains of to the monument in 1958 record was and distance from	he 1958 NBTs were place and made ne not recovered. R m the two 1958 Ce	not recovered. The witnesses as desembled the control of the contr	The monu scribed orner in	ment below the	is at remai	t a fe	nce co the N	rner wi -S fend	ith o	lđ ted i	n
C. Description of monument for corne	r and accessories	established to perp	etuate locating the	position	of th	e cor						
(M1) Found 1"ID I.pipe with 4" brass Dept. of Conservation cap. Set measuring nail with tag in: 10" M.Birch S25E 32.35' mrkd "S6 NBT 10" W.Birch S61E 25.45' do 8" Balsam South 33.85' mrkd "S1 NBT 5" Balsam N47E 33.4' mrkd "S31 NB Bearings are magnetic. Distances are nail with tag.	MDNR ca in: "12" Ced 18" Ced "6" W.Bi I" 6" W.Bi	ar N89W 37.3' m	nails with tags  rkd "1/45" *  rkd "1/45" *  rkd "1/45 HBT"  do  Distances are to	Stey		SUR	ZKOSŁ NND VEYOR 1986		les	<i>(.</i> •		
Signed by Stephen S.	zytylust		Date	/	2/	7 %	1					
Surveyor's Michigan License No	3398	4										