JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

Located in: Corner Code # Mackinac County T42N R01W 1. Public Land Survey T43N R01W 7.13 T R R T R Ţ 2. Property Controlling S R Т in Section S Т R S Miscellaneous S R Property in Sec.

4. Lot No. , Recor

, Recorded Plat

5. Private Claims

I, Neil E Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes James Mullett	8" Tamarack 16" Birch	N 72 E N 44 W	7 lks 11 lks
1970 DNR Billy Buckler Set 1" pipe and DNR cap From original BT Liber 2, Page 638	12" Cedar 7" Cedar	S 62 E Due N	30.5' 27.5'
1992 S Kass Fd 1" pipe and broken cap Liber D, Page 163	7" Cedar 20" Hemlock 14" Hemlock 8" Cedar	Due N S 56 E S 35 W N 59 E	27.10' 24.50' 24.54' 27.63'


DIANE FRANKOVICH
MACYINAC COUNTY REGISTE, OF DEEDS

DEC 3 1 1998

AM PM 7|8|9|10|11|12|1|2|3|4|5|6

<u>.</u>

Register of Deeds Stamp & File Number



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998 Fd 1" pipe, broken cap and 4 witness trees
Original Y Birch BT is now up-rooted and down to NW
Accepted corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is 1" pipe with a broken DNR cap Corner is on North edge of E-W snowmobile trail Corner is partially protected by rootball of downed BT

7" Cedar	Due N	27.10'	(Old)
20" Hemlock	S 56 E	24.50'	(Old)
14" Hemlock	S 35 W	24.54'	(Old)
8" Cedar	N 59 E	27.63'	(Old)



Bearings are compass bearings, corrected for declination, all distances are to a 20 penny nail in the side of the witness object unless otherwise noted.

Date

Signed by <u>Neil E. Hiel P.S.</u>

12-29-98

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197'
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995