LAND CORNER RECORLATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LOCATED IN -: CORNER CODE NUMBER

Mackinac Co.

FOR CORNERS OF -:

2 Corners

•	W CONTENT OF THE CONT
1	PUBLIC LAND SURVEY T. 43 S., R. 7 W. H-13, I-13
:	PROPERTY CONTROLL- ING IN SECTION, T S., R W.
	MISCELLANEOUS PROPERTY IN SECTION, T
4	LOT NO, RECORDED PLAT
5	PRIVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER
r a I a	David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, e corner points mentioned in lines 1 and 2 above were, in a field survey on
Å	Description of original monument and accessories and/or subsequent restoration:
-13	Scuth 1/4 corner of sec. 34. Wood Post, Leech 12", N82°E, 10 lks. & Beech 14", N15°W, 30 lks.
-13	Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.J.L. betw. the SE and SW sec. cors. of sec. 34.
-13	Re-witnessed sec. cor. as set by Billy D. Buckler, R.L.S. in 1963. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
-13	D.E.R. Nonument. New Bearings: I-13 D.N.R. Monument. New Bearings:
	71 R. Pine, S20 E, 20.1 16" R. Pine, S38°E, 80.2 15" R. Pine, N60°E, 9.4 10" R. Pine, S06°E, 66.8 10" R. Pine, N08°E, 24.6 10" R. Pine, S33°W, 59.8 15" R. Pine, S82°W, 30.4 1
	Nonu. :/; cor. northside of sec. 3, 33.94 West.
s	CNED BY David B. Babbitt DATE 8-3-82
S	RVEYOR'S MICHIGAN REGISTRATION NO. 21588 (SEAL)
	F STATE AND UNITED STATES AGENCIES: