## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR	CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER		
1. P	UBLIC LAND SURVEY	T S., R §	E		
2. P	ROPERTY CONTROLL- 3	,T43N73	13, 9		
		, T N N N V			
4. L	OT NO, RE	CORDED PLAT			
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER	
1	David B. Habbitt	, do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970,	
Bure and as ea	eau of Land Management of <b>abo</b> ve were, in <b>a</b> field sur	r by a decree of a court of la vey on	w. Furthermore, that the corne , 19, found, recovered, res	States Department of the Interior, r points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a	
<b>A</b> .	Description of original mon	ument and accessories and/o	or subsequent restoration:		
13	13 Southeast 1/16 corner of section 3. billy D. Buckler, RLS in 1981. 8" Gedar, S78°W, 20.6' & 16" Gedar, N15°E, 11.2'.				
9	East 1/16 corner of section 3. Lilly D. Buckler, RLS in 1981. 10" k. Fine, S36°W, 56.4' & 10" k. Pine, S8°E, 59.7'.				
В. І	Description of corner evide	nce found and/or method ap	oplied in restoring or re-establishin	ng corner:	
13	Corner adjusted to new location of east 1/4 corner of section 4. Corner placed at intersection of lines connecting opposite 1/16 corners.				
9	9 Corner adjusted to new location of east 1/4 corner of section 4. Corner placed midway and on line bet. 1/4 corner east and center corner west.				
<b>C</b> . 1	Description of monument for	or corner and accessories esta	ablished to perpetuate locating the	e position of the corner:	
	Mounment at both		<u> </u>		
13	6" Cedar, West, 16" Cedar, N22°E 8" Cedar, S68°W 4" Cedar, S22°E	, 21.7'	9 16" H. Maple, No. 5" Spruce, Es 10" R. Pinè, Sc. 10" h. Pine, Sc.	62°W, 60.6' ast, 8.9' 08°E, 67.9' 31°W, 63.2'	

SIGNED BY David E. Eabtit Ward B. Ballit DATE 11-21-83

SURVEYOR'S MICHIGAN RECISTRATION NO. 21558

(SEAL)