LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R F	i	
2. PROPERTY CONTROLL- ING IN SECTION—9			
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E	;;	
4. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
re-established, monumented, re and rules therefore as required Bureau of Land Management of and 5 above were, in a field sur	e-monumented, recovered or in the current manual of sur or by a decree of a court of la- evey on	restored as expressed below and every instructions of the United Sw. Furthermore, that the corne, 19, found, recovered, res	of P.A. 74, Michigan P.A. of 1970, 6-3, 1983, established, d in conformance with regulations States Department of the Interior, or points mentioned in lines 3, 4 tored, established or re-established tration for Land Surveyors or, by a
A. Description of original mor	nument and accessories and/o	r subsequent restoration:	
5 North 1/16 corne	r of section 9. Not	prev. set.	·
F-4 Center of section	n 9. Not prev. set.		
5 Corner set M.P.O	.L. between center co	plied in restoring or re-establishing or re-establishing or ner and computed Nort reh and was not set.	ng corner: h 1/4 corner of section 9.
, ,	_	nd E-W 1/4 lines of sec	. 9.
C. Description of monument f	or corner and accessories esta	blished to perpetuate locating the	e position of the corner:
1" pipe buried at bot	h corners. Bearings		
5 8" H. Maple, N62° 8" H. Maple, N82° 6" H. Maple, \$20° 7" H. Maple, N21°	E, 35.0' E, 59.2'	F-4 Tag in 14" R.Map Tag in Power Pol Tag in 10" H. Ma Tag in 14" Baech	.e, N86°W, 32.65' ple, S23°W, 86. 58
	00 1 00:44	<u>-</u>	and the same of th

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)